



Air Suspension Products

2018 PRODUCT CATALOG

ENGINEERED TO RIDE,
BUILT TO LAST







THE ARNOTT ADVANTAGE



Arnott Air Suspension Products is the industry leader in aftermarket air suspension parts and accessories for luxury cars, pick-up trucks, and SUVs.

Arnott serves the world with multiple warehouses, an impressive and ever-expanding research and development facility, plus unrivaled product availability through premier auto parts distributors.

Arnott's long and impressive record of accomplishments is the result of painstaking dedication to:

-  High quality, affordable aftermarket air suspension replacement products
-  Professional, personable customer service
-  Fast shipping available through Arnott's network of distributors
-  Superior warranties and support

THE BROADEST COVERAGE OF QUALITY AIR SUSPENSION PRODUCTS & OPTIONS

Arnott offers more than 300 quality aftermarket air suspension products covering nearly 800 applications including OES Air Suspension Compressors, new Air Springs, Arnott-designed new Air Struts, remanufactured OE Air Struts, and Coil Spring Conversion Kits.

WARRANTIES

Arnott offers a Limited Lifetime Warranty for European Union and North American customers on all Air Springs, new and remanufactured Air Strut and Shock Assemblies, Coil Spring Conversion Kits, and Air Suspension Compressors. Orders from elsewhere are backed by a Limited Two-Year Warranty.

Arnott's warranty is non-transferable. Defective parts will be either replaced or repaired, if the part is within the warranty period and proof of purchase is provided. Arnott offers a 30-Day Warranty for parts used in commercial vehicles. Improper use or installation is not a manufacturer's defect.



with new Arnott air struts.

TABLE OF CONTENTS

| Product Features | | Vehicle Application List | |
|--------------------------------|-------|--------------------------|-------|
| The Arnott Advantage | 1 | Audi | 3 |
| What is Air Suspension? | 4 | Bentley | 5 |
| Tips & Tricks | 6 | BMW | 7-8 |
| Product Features | 31-32 | Cadillac | 9-10 |
| Tips & Tricks | 33 | Citroën | 11 |
| Product In-Depths | | Ford/Lincoln/Mercury | 13-14 |
| Air Springs | 12 | General Motors | 15-16 |
| Arnott-Designed New Air Struts | 18 | Jaguar | 17 |
| Remanufactured Air Struts | 22 | Jeep | 19 |
| OES Air Suspension Compressors | 30 | Land Rover | 20 |
| Reference | | Maybach | 21 |
| OEM Cross Reference Table | 34-41 | Mercedes-Benz | 23-26 |
| Contact | | Peugeot | 27 |
| Contact Arnott | 42 | Porsche/Volkswagen | 28 |
| | | Toyota/Lexus | 29 |

ARNOTT NEW AIR SPRING: A-2869

- New Arnott Front Air Spring for the Audi A6, C5 Chassis
- ContiTech Air Spring Bladder
- Custom-Molded Nylon Cap & Piston
- New O-rings Included
- New Upper Mount Included
- Engineered in the USA and Assembled in the EU



AIR SUSPENSION BASICS

Air Suspension is a type of vehicle suspension that is powered by an Air Suspension Compressor. The Height Sensors give the Air Suspension ECU a signal when the vehicle is not on the predetermined height level. The Air Suspension Compressor then pumps air into the Air Springs until the height level is reached. Air Struts and Air Springs are wear & tear parts, especially due to the rubber air spring. On average, an Air Suspension part needs to be replaced between 6 to 10 years because the rubber will dry out. Mileage, area and off-road usage also influence the replacement rate.

DIAGNOSING & REPAIRING IS EASY!

With Air Suspension it is quite obvious when the Air Strut or Air Spring is not functioning correctly. Usually the vehicle cannot level anymore or it drops on the side, even to the point where the vehicle is laying on its bump stops. It is important to change the broken parts in time because if the vehicle is being driven too long with an air suspension problem, the compressor will also burn or wear out. This will cause additional expenses. If the Air Suspension of a car is no longer functioning, the customer is usually not capable of driving the car comfortable anymore. Therefore, the broken or worn out parts needs to be replaced as quickly as possible. With Air Suspension parts now available in the independent aftermarket, Arnott offers customers a high quality alternative backed by superior warranties at an affordable price.

BENEFITS OF ARNOTT'S AIR SUSPENSION

- Highest Quality with Superior Warranties
- Broadest Aftermarket Assortment
- Super Simple Diagnosis & Installation
- Additional Turnover
- Additional Savings for the Workshop Customer

| Year | Sub-Model Information | Air Springs | | New Air Struts/Shocks | | Remanufactured OE Struts/Shocks | | Coil Spring Conversion Kits | Air Suspension Compressors |
|--|-------------------------------------|----------------------|----------------------|-----------------------|--------------------------|---------------------------------|------------|---|----------------------------|
| | | FRONT | REAR | FRONT | REAR | FRONT | REAR | | |
| A6/S6, ALLROAD, AVANT <i>See footnotes for additional part information</i> | | | | | | | | | |
| 1997-2005 | C5 Chassis w/ Rear Levelling | | A-2133 | | SK-2805 ³⁶ | | | | P-2134 |
| | | | A-2731 ²⁰ | | | | | | |
| 2000-2005 | C5 Chassis w/4 Corner Air Levelling | A-2869 | A-2133 | SK-2779 ³⁶ | SK-2805 ³⁶ | | | C-2718 ³ ²⁵ | P-2134 |
| | | A-2885 ²⁰ | A-2731 ²⁰ | | | | | | |
| 2003-2011 | C6 Chassis | | A-2960 | RT AS-2816 | | | | | P-2984 |
| | | | | LT AS-2817 | | | | | |
| A8/S8 <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2002-2010 | D3 Chassis (Normal) | | | RT AS-2775 | RT AS-3030 ³⁰ | RT AS-2560 | RT AS-2958 | C-3022 ³⁰ | P-2539 ³⁵ |
| | | | | LT AS-2776 | LT AS-3031 ³⁰ | LT AS-2561 | LT AS-2959 | | P-2599 ²⁹ |
| | D3 Chassis (Sport) | | | RT AS-2777 | RT AS-3032 ³⁰ | RT AS-2562 | RT AS-2965 | | P-2539 ³⁵ |
| | | | | LT AS-2778 | LT AS-3033 ³⁰ | LT AS-2563 | LT AS-2966 | | P-2599 ²⁹ |
| 2009-2017 | D4 Chassis (Normal) | | | | | AS-2864 | | P-2986 | |
| 2011-2017 | D4 Chassis (Sport) | | | | | AS-2865 | | P-2986 | |
| Q7 <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2006-2015 | | RT | A-2571 | A-2523 | | | | C-2616 ³ ²⁵ ³⁵ | P-2496 |
| | | LT | A-2572 | | | | | | |

³ Complete 4-Wheel Kit ²⁹ Diesel Engines Only ³⁶ Shock Only
²⁰ Generation-II/High Performance Spring Rate ³⁰ Coming Soon
²⁵ Includes Shocks ³⁵ Gas Engines Only

LT Left RT Right





WARNING LIGHTS?

Is there a warning light lit on the dashboard or is the car no longer levelled in the morning? Then there is most likely an air suspension problem.

COMPRESSOR PROBLEMS?

Is the compressor not functioning? The cause is usually a leakage. Make sure you also take care of that, otherwise the new compressor will break down as well (no warranty!).

CAR HEIGHT

The height of the car is not determined by the air spring but by the height sensor.

REPLACING REAR AIR SPRINGS

The rear air springs of the E-Class must be replaced in pairs. Due to an improvement in design, there is a resistance difference between Arnott and OE air springs. Due to this, Arnott and OE air springs 'cannot be used together'.

LEAKS?

A leakage is easy to find with a water and soap solution.

SOFTWARE UPDATES

The Land Rover LR3, LR4 and Range Rover Sport compressor might need a software update. This is due to a change from Land Rover in compressor supplier, from Hitachi to another brand. Without this update the compressor does not function well and you have no warranty.

ARNOTT REMANUFACTURED AIR STRUT: AS-2580

- Remanufactured in the USA Exclusively for Bentley Continental GT & Bentley Flying Spur
- ContiTech Air Spring Bladder
- New Terminal, Air Valve & Mount
- Anodized Aluminum Finish
- Pre-Assembled For Easy Installation



| Year | Sub-Model Information | Air Springs | | New Air Struts/Shocks | | Remanufactured OE Struts/Shocks | | Coil Spring Conversion Kits | Air Suspension Compressors |
|---|-----------------------|-------------|------|-----------------------|--------------------------|---------------------------------|------------|-----------------------------|----------------------------|
| | | FRONT | REAR | FRONT | REAR | FRONT | REAR | | |
| CONTINENTAL GT <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2003-2017 | | | | RT AS-2892 | RT AS-3129 ³⁰ | RT AS-2580 | RT AS-2968 | | P-2740 |
| | | | | LT AS-2893 | LT AS-3130 ³⁰ | LT AS-2581 | LT AS-2969 | | |
| FLYING SPUR <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2005-2013 | | | | RT AS-2892 | RT AS-3129 ³⁰ | RT AS-2580 | RT AS-2968 | | P-2740 |
| | | | | LT AS-2893 | LT AS-3130 ³⁰ | LT AS-2581 | LT AS-2969 | | |

³⁰ Coming Soon

LT Left RT Right

**PRODUCTS FOR
BMW**

[re]built to last.



ASK FOR ARNOTT.

ARNOTT NEW AIR SPRING: A-2780

- New Arnott Rear Air Spring for the BMW 5 Series, F07 and F11 Chassis
- New Premium Brand Air Spring Bladder
- Heavy-Duty Crimping Rings
- Fits Left or Right Side
- 4mm Quick Connect Airline Fitting
- Superior Warranties




| Year | Sub-Model Information | Air Springs | | New Air Struts/Shocks | | Remanufactured OE Struts/Shocks | | Coil Spring Conversion Kits | Air Suspension Compressors | |
|---|--|-------------|--------------|-----------------------|------------|---------------------------------|------|-----------------------------|----------------------------|-----------|
| | | FRONT | REAR | FRONT | REAR | FRONT | REAR | | | |
| X5 SERIES <i>See footnotes for additional part information</i> | | | | | | | | | | |
| 2000-2006 | E53 Chassis w/4 Corner Air Levelling Only, Comfort | RT A-2861 | 24 RT A-2501 | RT AS-2764 | | RT AS-2305 | | C-2664 | 3 30 | P-2494 |
| | | LT A-2862 | 24 LT A-2502 | LT AS-2765 | | LT AS-2306 | | | | |
| | E53 Chassis w/4 Corner Air Levelling Only, Sport | RT A-2861 | 24 RT A-2503 | RT AS-2764 | | RT AS-2305 | | C-2664 | 3 30 | P-2494 |
| | | LT A-2862 | 24 LT A-2504 | LT AS-2765 | | LT AS-2306 | | | | |
| | E53 Chassis w/Rear Air Leveling Only, Comfort | | RT A-2501 | | | | | C-2665 | 5 30 | P-2469 |
| | | | LT A-2502 | | | | | | | |
| | E53 Chassis w/Rear Air Levelling Only, Sport | | RT A-2503 | | | | | C-2665 | 5 30 | P-2469 |
| | | | LT A-2504 | | | | | | | |
| 2007-2013 | E70 Chassis | | A-2642 | | | | | | | P-3221 28 |
| X6 SERIES <i>See footnotes for additional part information</i> | | | | | | | | | | |
| 2009-Present | E71 Chassis | | A-2642 | | | | | | | P-3221 28 |
| 5 SERIES <i>See footnotes for additional part information</i> | | | | | | | | | | |
| 1997-2004 | E39 Chassis, Wagon w/Rear Air Levelling | | RT A-2738 | | | | | | | P-2469 |
| | | | LT A-2737 | | | | | | | |
| 2004-2010 | E61 Chassis, Wagon w/Rear Air Levelling | | A-2755 | | | | | C-3013 | 30 | P-3220 28 |
| 2010-2017 | F07, F11 Chassis, Grand Turismo & Wagon | | A-2780 37 | | | | | | | P-2985 |
| 7 SERIES <i>See footnotes for additional part information</i> | | | | | | | | | | |
| 2002-2008 | E65, E66 Chassis, Rear Air Levelling w/EDC | | | | RT AS-2978 | | | C-3019 | 30 | P-2469 |
| | | | | | LT AS-2979 | | | | | |
| | E65, E66 Chassis, Rear Air Levelling w/o EDC | | | | RT AS-2980 | | | C-3019 | 30 | P-2469 |
| | | | | | LT AS-2981 | | | | | |
| 2009-2015 | F01, F02 Chassis | | | | | | | | | P-2985 |

| Year | Sub-Model Information | Valve Blocks | Dryers |
|------------------|---|--------------|--------|
| X5 SERIES | | | |
| 2007-2013 | E70 Chassis | K-2898 | |
| X6 SERIES | | | |
| 2008-2014 | E71 Chassis | K-2898 | |
| 5 SERIES | | | |
| 2004-2010 | E61 Chassis, Wagon w/Rear Air Levelling | K-2897 | |

- 3 Complete 4-Wheel Kit
- 5 Rear only
- 24 New Air Spring Only, Reuse Factory Shock
- 28 Plug & Play Complete Assembly
- 30 Coming Soon
- 37 Not Applicable for BMW's with Integral Active Steering

LT Left RT Right

PRODUCTS FOR CADILLAC



AIR SUSPENSION COMPRESSOR: P-2793

- One Compressor Fits Multiple Large GM SUV Applications Including the Escalade
- Included Wiring Harnesses Mate with Second & Third Generation Vehicles
- Pre-Installed with New Bracket & Dryer for Fast Installation
- Durability Tested by Arnott to Reduce Returns
- Detailed Installation Manual Available

| Year | Sub-Model Information | Air Springs | | New Air Struts/Shocks | | Remanufactured OE Struts/Shocks | | Coil Spring Conversion Kits | Air Suspension Compressors |
|--|-----------------------|-------------|------|-----------------------|----------------------|---------------------------------|------|-----------------------------|----------------------------|
| | | FRONT | REAR | FRONT | REAR | FRONT | REAR | | |
| ALLANTE <i>See footnotes for additional part information</i> | | | | | | | | | |
| 1993 | All Models | | | SK-2162 ¹ | SK-2111 ¹ | | | | |
| DEVILLE <i>See footnotes for additional part information</i> | | | | | | | | | |
| 1994 | Base Model Only | | | SK-2264 ¹ | AS-2125 ¹ | | | | |
| | Concours Only | | | SK-2162 ¹ | AS-2163 ¹ | | | | |
| 1995 | Base Model Only | | | SK-2118 ¹ | AS-2125 ¹ | | | | |
| | Concours Only | | | SK-2167 ¹ | AS-2163 ¹ | | | | |
| 1996 | Base Model Only | | | SK-2167 ¹ | AS-2163 ¹ | | | | |
| | Concours Only | | | SK-2176 ¹ | AS-2177 ¹ | | | | |
| 1997-1999 | Base Model Only | | | SK-2183 ¹ | AS-2185 ¹ | | | | |
| | Concours Only | | | SK-2178 ¹ | AS-2177 ¹ | | | | |
| 2000-2005 | Base & DHS Model | | | SK-2189 ¹ | AS-2190 ¹ | | | | |
| | DTS Only | | | SK-2186 ¹ | AS-2121 ¹ | | | | |
| DTS <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2006-2011 | w/Magne-Ride | | | SK-2952 | AS-2950 | | | | P-2982 |
| | w/o Magne-Ride | | | SK-2189 ¹ | AS-2190 ¹ | | | | P-2982 |
| ELDORADO <i>See footnotes for additional part information</i> | | | | | | | | | |
| 1993 | ETC Model Only | | | SK-2162 ¹ | AS-2163 ¹ | | | | |
| | Non ETC Models | | | SK-2264 ¹ | AS-2125 ¹ | | | | |
| 1994 | All Models | | | SK-2162 ¹ | AS-2163 ¹ | | | | |
| 1995 | All Models | | | SK-2167 ¹ | AS-2163 ¹ | | | | |
| 1996 | Base Model Only | | | SK-2167 ¹ | AS-2163 ¹ | | | | |
| | ETC Model Only | | | SK-2176 ¹ | AS-2177 ¹ | | | | |
| 1997-2002 | Base Model Only | | | SK-2183 ¹ | AS-2185 ¹ | | | | |
| | ETC Model Only | | | SK-2178 ¹ | AS-2177 ¹ | | | | |

¹ Sold In Pairs

| Year | Sub-Model Information | Air Springs | | New Air Struts/Shocks | | Remanufactured OE Struts/Shocks | | Coil Spring Conversion Kits | Air Suspension Compressors |
|--|------------------------------|-------------|------|-----------------------|-----------------------|---------------------------------|---------|--|----------------------------|
| | | FRONT | REAR | FRONT | REAR | FRONT | REAR | | |
| ESCALADE <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2002-2006 | All Models (Excl. ESV & EXT) | | | SK-3062 ⁶ | AS-2700 ²³ | | AS-2708 | C-3182 ³ ⁶ ²⁵ | P-2793 ²⁸ |
| | | | | SK-2760 | AS-2715 | | | C-2666 ³ ²⁵ | |
| | ESV & EXT Only | | | SK-3062 ⁶ | AS-2700 ²³ | | AS-2708 | C-3183 ³ ⁶ ²⁵ | P-2793 ²⁸ |
| | | | | SK-2760 | AS-2715 | | | C-2667 ³ ²⁵ | |
| 2007-2014 | All Models (Excl. ESV & EXT) | | | SK-2954 ²³ | AS-2700 ²³ | | AS-2708 | C-3184 ³ ⁶ ²⁵ | P-2793 ²⁸ |
| | | | | SK-2806 | AS-2715 | | | C-2835 ³ ²⁵ | |
| | ESV & EXT Only | | | SK-2954 ²³ | AS-2700 ²³ | | AS-2708 | C-3185 ³ ⁶ ²⁵ | P-2793 ²⁸ |
| | | | | SK-2806 | AS-2715 | | | C-2836 ³ ²⁵ | |
| SEVILLE <i>See footnotes for additional part information</i> | | | | | | | | | |
| 1993 | SLS Only | | | SK-2264 ¹ | AS-2125 ¹ | | | | |
| | STS Only | | | SK-2162 ¹ | AS-2163 ¹ | | | | |
| 1994 | SLS & STS | | | SK-2162 ¹ | AS-2163 ¹ | | | | |
| 1995 | SLS & STS | | | SK-2167 ¹ | AS-2163 ¹ | | | | |
| 1996 | SLS Only | | | SK-2167 ¹ | AS-2163 ¹ | | | | |
| | STS Only | | | SK-2176 ¹ | AS-2177 ¹ | | | | |
| 1997 | SLS & STS | | | SK-2178 ¹ | AS-2177 ¹ | | | | |
| 1998-2001 | SLS Only | | | SK-2186 ¹ | AS-2121 ¹ | | | | |
| 1998-2003 | STS Only | | | SK-2186 ¹ | AS-2121 ¹ | | | | |
| 2001-2004 | SLS Only | | | SK-2189 ¹ | AS-2190 ¹ | | | | |

| Year | Sub-Model Information | Valve Blocks | Dryers |
|-----------------|-----------------------|--------------|--------|
| ESCALADE | | | |
| 2002-2014 | | | D-2803 |

- ¹ Sold In Pairs
- ³ Complete 4-Wheel Kit
- ⁶ Eibach Strut/Shock
- ²³ Arnott Premium Quality
- ²⁵ Includes Shocks
- ²⁸ Plug & Play Complete Assembly





AIR SUSPENSION COMPRESSOR: P-2854

- New OES Air Suspension Compressor for Citroën C4 Grand Picasso
- Pre-Assembled in the EU for Easy Installation
- Compatible with OE Air Lines
- Integrated Relay
- Fully Tested
- Installation Manual Available
- Superior Warranties



- ▲ Fastest & Least Expensive Air Suspension Repair Option
- ▲ Premium Brand, Multi-Ply Air Bladders Last Longer
- ▲ Engineered to Provide a Luxury Ride
- ▲ Innovative Designs Are Easier to Install – Up to 94% Faster Than OE

Most air suspension problems occur because one or more of a vehicle's air springs have deteriorated because of age, driving conditions, dry rot, or road debris damage. Many low-quality knockoffs as well as some stock air springs are built with thin rubber air bladders and seals along with weak crimping rings. Arnott Air Springs are specifically designed to eliminate these common problem areas so they last longer while providing an outstanding ride.

Arnott Air Springs are engineered in the company's over 6,000 square meter Research and Development Center and then undergo extensive testing on Arnott-owned vehicles. Arnott springs feature state-of-the-art, multi-ply air bladders manufactured by industry-leading rubber companies such as ContiTech, Firestone

and Goodyear. Arnott springs are assembled, tested, and packaged in Arnott's American and EU facilities. Arnott Air Springs last longer, are easier to install, and provide unparalleled ride comfort and durability.

Several Arnott-designed air springs are so innovative they are patented in the USA or are patent-pending. For example, to save installation time and costs, Arnott engineers developed air springs for the Mercedes-Benz W211 E-Class and W219 CLS-Class vehicles that do not require the removal of the vehicle's rear end to access the air tank. By optimizing the internal piston and bladder, Arnott Air Springs save mechanics more than 90% in installation time.

| Year | Sub-Model Information | Air Springs | | New Air Struts/Shocks | | Remanufactured OE Struts/Shock | | Coil Spring Conversion Kits | Air Suspension Compressors |
|--|-----------------------|-------------|----------------------|-----------------------|------|--------------------------------|------|-----------------------------|----------------------------|
| | | FRONT | REAR | FRONT | REAR | FRONT | REAR | | |
| C4 <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2006-2013 | Grand Picasso | | A-2939 | | | | | C-3015 ³⁰ | P-2854 |
| 2014 | Grand Picasso | | A-2939 | | | | | | |
| JUMPY <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2007-2016 | | | A-2938 ³⁰ | | | | | | P-2851 |

³⁰ Coming Soon

ARNOTT OFFERS AIR SPRINGS FOR

*Audi • BMW • Citroen • Ford • GM • Jeep • Land Rover • Lincoln • Mercury
Mercedes-Benz • Porsche/Volkswagen • Toyota/Lexus*

PRODUCTS FOR FORD/LINCOLN/ MERCURY

ARNOTT NEW AIR SPRING: A-2647

- Works with the Factory Load Leveling Functionality on the Navigator & Expedition
- Heavy Duty ContiTech Air Bladder Designed for These Heavy SUVs
- Reuses Factory Shock to Save Money
- Includes O-Rings for More Reliable Installation
- Replace in Pairs for Excellent Ride Comfort & Stability



| Year | Sub-Model Information | Air Springs | | New Air Struts/Shocks | | Remanufactured OE Struts/Shocks | | Coil Spring Conversion Kits | Air Suspension Compressors | |
|---|-----------------------|-------------|--------|-----------------------|---------|---------------------------------|---------|-----------------------------|----------------------------|--------|
| | | FRONT | REAR | FRONT | REAR | FRONT | REAR | | | |
| FORD CROWN VICTORIA <i>See footnotes for additional part information</i> | | | | | | | | | | |
| 1992-2002 | 4,6 Liter V8 | | A-2105 | | | | | C-2614 | 5 25 | P-2936 |
| | | | | A-2220 | 9 | | | | | |
| 2003-2011 | | | A-2105 | | | | | C-2615 | 5 25 | P-2936 |
| | | | A-2220 | 9 | | | | | | |
| FORD EXPEDITION/LINCOLN NAVIGATOR <i>See footnotes for additional part information</i> | | | | | | | | | | |
| 1997-2002 | 2WD | | A-2148 | | | | | C-2607 | 5 25 | P-2932 |
| | 4WD | | A-2153 | | | | | C-2608 | 5 25 | P-2932 |
| 2003-2006 | 2WD, 4WD | A-2143 | A-2735 | 24 | AS-2139 | 15 | SK-2723 | C-2140 | 3 25 | P-2932 |
| | | | | | | | | C-2293 | 3 18 | |
| 2007-2017 | Base & EL/L, 2WD, 4WD | | A-2647 | 24 | | | | C-2529 | 5 25 | P-2937 |

- | | | |
|--------------------------------|--|--------------------|
| 3 Complete 4-Wheel Kit | 15 Strut, Air Spring, & Upper Mount Assembly | 25 Includes Shocks |
| 5 Rear Only | 18 2" Lowered Kit/Premium Shocks | 30 Shock Only |
| 9 Heavy Duty For Limousine Use | 24 New Air Spring Only, Reuse Factory Shock | |

| Year | Sub-Model Information | Air Springs | | New Air Struts/Shocks | | Remanufactured OE Struts/Shocks | | Coil Spring Conversion Kits | Air Suspension Compressors | |
|---|-----------------------|-------------|--------|-----------------------|--------|---------------------------------|------|-----------------------------|----------------------------|--------|
| | | FRONT | REAR | FRONT | REAR | FRONT | REAR | | | |
| FORD WINDSTAR <i>See footnotes for additional part information</i> | | | | | | | | | | |
| 1995-2003 | w/Rear Levelling | | | | | | | C-2175 | 5 | |
| LINCOLN CONTINENTAL <i>See footnotes for additional part information</i> | | | | | | | | | | |
| 1984-1987 | 5,0 Liter V8 | A-2106 | A-2107 | | | | | C-2224 | 3 | P-2231 |
| 1995-1996 | 4,6 Liter V8 | A-2174 | A-2173 | 24 RT | | | | C-2168 | 3 25 | P-2211 |
| | | | | LT | A-2212 | | | | | |
| 1997-2002 | 4,6 Liter V8 | | A-2173 | RT | | | | C-2180 | 5 | P-2211 |
| | | | A-2212 | LT | | | | | | |
| LINCOLN MARK VII (7) <i>See footnotes for additional part information</i> | | | | | | | | | | |
| 1984-1992 | All, 5,0 Liter V8 | A-2106 | A-2107 | | | | | C-2224 | 3 | P-2231 |
| LINCOLN MARK VIII (8) <i>See footnotes for additional part information</i> | | | | | | | | | | |
| 1993-1998 | 4,6 Liter V8 | | A-2108 | | | SK-2225 | 1 | C-2236 | 3 25 | P-2210 |
| LINCOLN TOWN CAR <i>See footnotes for additional part information</i> | | | | | | | | | | |
| 1990-1997 | 4,6, 5,0 Liter V8 | | A-2105 | | | | | C-2614 | 5 25 | P-2936 |
| | | | A-2220 | 9 | | | | | | |
| 1998-2002 | 4,6 Liter V8 | | A-2105 | | | | | C-2614 | 5 25 | P-2935 |
| | | | | A-2220 | 9 | | | | | |
| 2003-2011 | | | A-2105 | | | | | C-2615 | 5 25 | P-2936 |
| | | | A-2220 | 9 | | | | | | |
| MERCURY GRAND MARQUIS <i>See footnotes for additional part information</i> | | | | | | | | | | |
| 1992-2002 | 4,6 Liter V8 | | A-2105 | | | | | C-2614 | 5 25 | P-2936 |
| | | | | A-2220 | 9 | | | | | |
| 2003-2011 | | | A-2105 | | | | | C-2615 | 5 25 | P-2936 |
| | | | A-2220 | 9 | | | | | | |

| Year | Sub-Model Information | Valve Blocks | Dryers |
|--|-----------------------|--------------|--------|
| FORD CROWN VICTORIA | | | |
| 1992-2011 | 4,6 Liter V8 | | D-2171 |
| FORD EXPEDITION/LINCOLN NAVIGATOR | | | |
| 1997-2006 | 2WD, 4WD | | D-2155 |
| LINCOLN CONTINENTAL | | | |
| 1984-1987 | 5,0 Liter V8 | | D-2155 |
| 1988-1994 | 3,8 Liter V6 | | D-2155 |
| 1995-2002 | 4,6 Liter V8 | | D-2171 |
| LINCOLN MARK VII (7) | | | |
| 1984-1992 | All, 5,0 Liter V8 | | D-2155 |
| LINCOLN MARK VIII (8) | | | |
| 1993-1998 | 4,6 Liter V8 | | D-2155 |
| LINCOLN TOWN CAR | | | |
| 1990-1997 | 4,6, 5,0 Liter V8 | | D-2171 |
| 1998-2002 | 4,6 Liter V8 | | D-2155 |
| 2003-2011 | 4,6 Liter V8 | | D-2171 |
| MERCURY GRAND MARQUIS | | | |
| 1992-2011 | 4,6 Liter V8 | | D-2171 |

- | | | |
|------------------------|--------------------------------|---|
| 1 Sold in Pairs | 5 Rear Only | 24 New Air Spring Only, Reuse Factory Shock |
| 3 Complete 4-Wheel Kit | 9 Heavy Duty For Limousine Use | 25 Includes Shocks |

LT Left RT Right

PRODUCTS FOR GENERAL MOTORS

| Year | Sub-Model Information | Air Springs | | New Air Struts/Shocks | | Remanufactured OE Struts/Shocks | | Coil Spring Conversion Kits | Air Suspension Compressors |
|--|-----------------------------------|-------------|---------------------|-----------------------|-----------------------|---------------------------------|---------|--|------------------------------------|
| | | FRONT | REAR | FRONT | REAR | FRONT | REAR | | |
| BUICK LE SABRE <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2000-2005 | | | | SK-2189 ¹ | AS-2190 ¹ | | | | |
| BUICK LUCERNE <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2006-2011 | w/Magne-Ride | | | SK-2952 | AS-2950 | | | | P-2982 |
| BUICK PARK AVENUE <i>See footnotes for additional part information</i> | | | | | | | | | |
| 1997 | | | | | AS-2190 ¹ | | | | |
| 1998-2004 | | | | SK-2189 ¹ | AS-2190 ¹ | | | | |
| BUICK RAINIER <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2004-2007 | | | A-2610 ⁷ | | | | | C-2137 ⁵ | P-2857 ²⁸ |
| BUICK RIVIERA <i>See footnotes for additional part information</i> | | | | | | | | | |
| 1995-1999 | | | | | AS-2190 ¹ | | | | |
| CHEVROLET AVALANCHE 1500 <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2003-2006 | 4x2, 4x4 w/ Electronic Suspension | | | SK-3062 ⁶ | AS-2700 ²³ | | AS-2708 | C-3182 ³ ⁶ ²⁵ | P-2793 ²⁸ ³² |
| | | | | SK-2760 | AS-2715 | | | C-2666 ³ ²⁵ | |
| 2007-2013 | | | | SK-2954 ²³ | AS-2700 ²³ | | AS-2708 | C-3184 ³ ⁶ ²⁵ | P-2793 ²⁸ ³² |
| | | | | SK-2806 | AS-2715 | | | C-2835 ³ ²⁵ | |
| CHEVROLET SUBURBAN 1500 <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2000-2006 | 4x2, 4x4 w/Autoride Suspension | | | SK-3062 ⁶ | AS-2700 ²³ | | AS-2708 | C-3183 ³ ⁶ ²⁵ | P-2793 ²⁸ ³² |
| | | | | SK-2760 | AS-2715 | | | C-2667 ³ ²⁵ | |
| 2007-2014 | | | | SK-2954 ²³ | AS-2700 ²³ | | AS-2708 | C-3185 ³ ⁶ ²⁵ | P-2793 ²⁸ ³² |
| | | | | SK-2806 | AS-2715 | | | C-2836 ³ ²⁵ | |
| CHEVROLET TAHOE 1500 <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2000-2006 | 4x2, 4x4 w/Autoride Suspension | | | SK-3062 ⁶ | AS-2700 ²³ | | AS-2708 | C-3182 ³ ⁶ ²⁵ | P-2793 ²⁸ ³² |
| | | | | SK-2760 | AS-2715 | | | C-2666 ³ ²⁵ | |
| 2007-2014 | 4x2, 4x4 w/ Electronic Suspension | | | SK-2954 ²³ | AS-2700 ²³ | | AS-2708 | C-3184 ³ ⁶ ²⁵ | P-2793 ²⁸ ³² |
| | | | | SK-2806 | AS-2715 | | | C-2835 ³ ²⁵ | |

| Year | Sub-Model Information | Valve Blocks | Dryers |
|---------------------------------|-----------------------------------|--------------|--------|
| CHEVROLET AVALANCHE 1500 | | | |
| 2003-2013 | 4x2, 4x4 w/Electronic Suspension | | D-2803 |
| CHEVROLET SUBURBAN 1500 | | | |
| 2000-2014 | 4x2, 4x4 w/Autoride Suspension | | D-2803 |
| CHEVROLET TAHOE 1500 | | | |
| 2000-2006 | 4x2, 4x4 w/Autoride Suspension | | D-2803 |
| 2007-2014 | 4x2, 4x4 w/ Electronic Suspension | | D-2803 |
| GMC YUKON 1500 | | | |
| 2000-2013 | All w/113" WB (Incl. Denali) | | D-2803 |
| 2000-2014 | XL w/129" WB (Incl. Denali) | | D-2803 |



- ¹ Sold In Pairs
- ³ Complete 4-Wheel Kit
- ⁵ Rear Only
- ⁶ Eibach Strut/Shock
- ⁷ Crimped Assembly, Improved Design
- ²³ Arnott Premium Quality
- ²⁵ Includes Shocks
- ²⁸ Plug & Play Complete Assembly
- ³² Bracket does not fit 2000 Model Year

COIL SPRING CONVERSION KIT: C-3185

- Premium Shocks & Components Designed for Large GM SUVs
- Eibach Shock Absorbers Engineered to Provide a Great Ride
- Specially Tuned Powder-Coated Rear Coil Springs Made from USA Steel
- Installation Manual & Video for a Fast, Flawless Installation
- Exclusive Electronic Bypass Module Turns Off Dashboard Warning Lights



| Year | Sub-Model Information | Air Springs | | New Air Struts/Shocks | | Remanufactured OE Struts/Shocks | | Coil Spring Conversion Kits | Air Suspension Compressors |
|---|------------------------------|-------------|---------|-----------------------|-----------------------|---------------------------------|---------|--|------------------------------------|
| | | FRONT | REAR | FRONT | REAR | FRONT | REAR | | |
| CHEVROLET TRAILBLAZER <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2002-2009 | All w/113" WB | | | A-2610 ⁷ | | | | C-2137 ⁵ | P-2857 ²⁸ |
| 2002-2006 | EXT w/129" WB | | | A-2610 ⁷ | | | | C-2285 ⁵ | P-2863 ²⁸ |
| GMC ENVOY <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2002-2009 | All w/113" WB | | | A-2610 ⁷ | | | | C-2137 ⁵ | P-2857 ²⁸ |
| 2002-2006 | XL w/129" WB | | | A-2610 ⁷ | | | | C-2285 ⁵ | P-2863 ²⁸ |
| | XUV w/129" WB | | | A-2610 ⁷ | | | | C-2285 ⁵ | P-2863 ²⁸ |
| GMC YUKON 1500 <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2000-2006 | All w/113" WB (Incl. Denali) | | | SK-3062 ⁶ | AS-2700 ²³ | | AS-2708 | C-3182 ³ ⁶ ²⁵ | P-2793 ²⁸ ³² |
| | | | | SK-2760 | AS-2715 | | | C-2666 ³ ²⁵ | |
| 2007-2013 | | | | SK-2954 ²³ | AS-2700 ²³ | | AS-2708 | C-3184 ³ ⁶ ²⁵ | P-2793 ²⁸ ³² |
| | | | SK-2806 | AS-2715 | | | | C-2835 ³ ²⁵ | |
| 2000-2006 | XL w/129" WB (Incl. Denali) | | | SK-3062 ⁶ | AS-2700 ²³ | | AS-2708 | C-3183 ³ ⁶ ²⁵ | P-2793 ²⁸ ³² |
| | | | | SK-2760 | AS-2715 | | | C-2667 ³ ²⁵ | |
| 2007-2014 | | | | SK-2954 ²³ | AS-2700 ²³ | | AS-2708 | C-3185 ³ ⁶ ²⁵ | P-2793 ²⁸ ³² |
| | | | SK-2806 | AS-2715 | | | | C-2836 ³ ²⁵ | |
| HUMMER H2 <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2002-2007 | All w/Rear Air Suspension | | | | | | | C-2987 | |
| 2008-2009 | | | | | | | | C-2988 | |
| OLDSMOBILE AURORA <i>See footnotes for additional part information</i> | | | | | | | | | |
| 1995-1997 | | | | | AS-2190 ¹ | | | | |
| 1998-2003 | | | | SK-2189 ¹ | AS-2190 ¹ | | | | |
| OLDSMOBILE BRAVADA <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2002-2004 | | | | | | A-2610 ⁷ | | C-2137 ⁵ | P-2857 ²⁸ |
| PONTIAC BONNEVILLE <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2000-2004 | | | | SK-2189 ¹ | AS-2190 ¹ | | | | |
| SAAB 9-7X <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2005-2009 | | | | | | A-2610 ⁷ | | C-2137 ⁵ | P-2857 ²⁸ |

- ¹ Sold In Pairs
- ³ Complete 4-Wheel Kit
- ⁵ Rear Only
- ⁶ Eibach Strut/Shock
- ⁷ Crimped Assembly, Improved Design
- ²³ Arnott Premium Quality
- ²⁵ Includes Shocks
- ²⁸ Plug & Play Complete Assembly
- ³² Bracket does not fit 2000 Model Year

ARNOTT-DESIGNED NEW AIR STRUTS



ARNOTT NEW AIR STRUT: AS-2888

- Fits Both X350 & X358 Jaguar XJ Chassis Applications
- New, Not Remanufactured, Shock Absorber & Strut Components
- Custom-Designed Monotube Shock Absorber
- CNC-Machined Aluminum Parts
- Anodized Aluminum Finish
- Pre-Assembled For Easy Installation



- ▲ Completely New Internal Shock with Zero Kilometers
- ▲ Custom-Valved Damper Provides Superior Ride
- ▲ Provides the Luxury, Comfort & Auto-Leveling of Air Suspension
- ▲ Enhanced Designs Improve Upon OE for Longer Life

Known for high-quality yet affordable Air Suspension components, Arnott continually seeks ways to save customers money while providing the best quality, the finest ride, and most exact fitment possible. After remanufacturing tens of thousands of OE struts year after year, Arnott engineers begin to note high failure rates in struts that cannot be rebuilt. The top and bottom mounts have aged and loosened, the internal shock is no longer fully functional, and they even find previously remanufactured struts.

Based on the company's unsurpassed experience with remanufactured struts, Arnott designs all-new struts engineered for each individual application. Arnott's completely new struts are built from the ground up with quality components including all-new, custom-valved internal shocks. These shocks are engineered and rigorously tested on dyno machines and then driven countless

kilometers on Arnott's fleet of test cars. The goal is to produce Air Struts capable of performing as close to the OE as possible ... and the proof is in the driving: most drivers love the new strut's ride, handling, and of course, the price! Many of Arnott's new struts feature CNC-machined tops made from aircraft-quality aluminium and new steel bottom mounts that fit perfectly without vehicle modifications. All Arnott Air Struts contain longer-lasting seals, new bump stops and heavy-duty crimping rings. Many feature dust baffles and aluminium cans to protect the units from road debris, and a resistor to eliminate dashboard warning lights.

Arnott-designed new struts are an excellent alternative for aging air suspension systems because they provide the luxury, comfort and auto leveling of air springs but replace the aging used stock shock with a completely new shock custom-valved to provide a great ride at a more affordable price.



ARNOTT OFFERS NEW AIR STRUTS FOR

Audi • Bentley • BMW • Cadillac • Ford • GM • Jaguar • Jeep • Land Rover
Lincoln • Mercedes-Benz • Porsche/Volkswagen • Toyota/Lexus

| Year | Sub-Model Information | Air Springs | | New Air Struts/Shocks | | Remanufactured OE Struts/Shocks | | Coil Spring Conversion Kits | Air Suspension Compressors |
|-----------|-----------------------|---|------|-----------------------|---------|---------------------------------|------|-----------------------------------|----------------------------|
| | | FRONT | REAR | FRONT | REAR | FRONT | REAR | | |
| XJ SERIES | | See footnotes for additional part information | | | | | | | |
| 2003-2007 | X350, Comfort | | | AS-2888 | AS-2889 | | | C-2745 ³ ²⁵ | P-2291 |
| | X350, Sport | | | AS-2890 | AS-2891 | | | C-2745 ³ ²⁵ | P-2291 |
| 2008-2010 | X358, Comfort | | | AS-2888 | AS-2889 | | | C-2745 ³ ²⁵ | P-2291 |
| | X358, Sport | | | AS-2890 | AS-2891 | | | C-2745 ³ ²⁵ | P-2291 |

³ Complete 4-Wheel Kit ²⁵ Includes Shocks

PRODUCTS FOR
JEEP

PRODUCTS FOR
LAND ROVER

Get the right
[re]man for
the job
Ask for Arnott.

ARNOTT NEW AIR SPRING: A-3010

- Easy-to-Install, Economical Design for the Jeep Grand Cherokee
- High Impact Upper & Lower Mounts Last Longer
- Multi-Ply Continental ContiTech Air Spring Bladder
- Arnott's New Spring Fits Both Sides
- Superior Warranties



| Year | Model | Air Springs | | New Air Struts/Shocks | | Remanufactured OE Struts/Shocks | | Coil Spring Conversion Kits | Air Suspension Compressors |
|---|-------------|-------------|--------|-----------------------|-----------------------|---------------------------------|------|-----------------------------|----------------------------|
| | | FRONT | REAR | FRONT | REAR | FRONT | REAR | | |
| GRAND CHEROKEE <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2011-2016 | WK2 Chassis | | A-3010 | | AS-3021 ³⁰ | | | | |

³⁰ Coming Soon

ARNOTT NEW AIR STRUT: AS-2809

- Fits Discovery 3, 4 and Range Rover Sport
- Custom-Designed Shock
- ContiTech Multi-Ply Air Bladder
- Black Anodized Aluminum Top
- Extra Heavy Duty Crimping Rings
- Superior Warranties



| Year | Sub-Model Information | Air Springs | | New Air Struts/Shocks | | Remanufactured OE Struts/Shocks | | Coil Spring Conversion Kits | Air Suspension Compressors |
|--|--|----------------------------------|----------------------------------|-----------------------|---------|---------------------------------|------|-----------------------------------|----------------------------|
| | | FRONT | REAR | FRONT | REAR | FRONT | REAR | | |
| DISCOVERY <i>See footnotes for additional part information</i> | | | | | | | | | |
| 1994-2002 | 2 (II) w/Air Suspension | | A-2202 | | | | | C-2203 ⁵ | P-2495 |
| 2004-2009 | 3/LR3 w/Air Suspension | | | AS-2809 | AS-2534 | | | C-2643 ³ ³⁰ | P-2815 ³³ |
| 2009-2017 | 4/LR4 w/Air Suspension | | | AS-2809 | AS-2534 | | | C-2643 ³ ³⁰ | P-2815 ³³ |
| RANGE ROVER <i>See footnotes for additional part information</i> | | | | | | | | | |
| 1994-2002 | P38A | A-2611 ⁷ ⁸ | A-2612 ⁷ ⁸ | | | | | C-2227 ³ | P-2514 |
| | | A-2691 ⁷ ⁸ | A-2692 ⁷ ⁸ | | | | | | |
| 2002-2005 | L322, MK-III, Vogue | RT A-2933 | A-2831 | RT AS-2961 | | | | C-2518 ³ | P-2462 |
| | | LT A-2934 | | LT AS-2962 | | | | | |
| 2005-2009 | Supercharged Only, L322, MK-III, Vogue, TDV8 3,6 | RT A-2933 | A-2831 | RT AS-2795 | | | | C-2145 ³ | P-3232 ³³ |
| | | LT A-2934 | | LT AS-2796 | | | | | |
| 2006-2012 | Excl. Supercharged, L322, MK-III, Vogue | RT A-2933 | A-2831 | RT AS-2961 | | | | C-2518 ³ | P-3232 ³³ |
| | | LT A-2934 | | LT AS-2962 | | | | | |
| 2010-2012 | L322 w/VDS, Vogue | RT A-2933 | A-2831 | RT AS-2797 | | RT AS-2757 | | C-2989 ³ | P-3232 ³³ |
| | | LT A-2934 | | LT AS-2798 | | LT AS-2758 | | C-2967 ³ ²⁵ | |
| 2012-2017 | L405 Chassis | | A-3025 ³⁰ | | | RT AS-3067 | | | |
| | | | | | | LT AS-3068 | | | |
| RANGE ROVER SPORT <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2005-2009 | Incl. Supercharged | | | AS-2809 | AS-2534 | | | | P-2815 ³³ |
| 2009-2013 | Supercharged Only | | | AS-2761 | AS-2762 | | | | P-2815 ³³ |
| | Excl. Supercharged | | | AS-2809 | AS-2534 | | | | P-2815 ³³ |
| 2013-2016 | L494 Chassis w/o CVD | | A-3027 ³⁰ | | | RT AS-3069 | | | |
| | | | | | | LT AS-3070 | | | |
| | L494 Chassis w/CVD | | | | | RT AS-3204 | | | |
| | | | | | | LT AS-3205 | | | |

- ³ Complete 4-Wheel Kit
- ⁵ Rear Only
- ⁷ Crimped Assembly, Improved Design
- ⁸ Extended Travel & Improved Ride
- ²⁵ Includes Shocks
- ³⁰ Coming Soon
- ³³ May Require a Software Update

LT Left RT Right

PRODUCTS FOR MAYBACH



ARNOTT REMANUFACTURED AIR STRUT: AS-2746

- Remanufactured in the USA Exclusively for Maybach 57 & 62
- Dyno Tested to Assure Full OE Functionality
- Thoroughly Cleaned and Repainted to Resist Corrosion
- New Continental ContiTech Air Spring Bladder Lasts Longer
- Superior Warranties



PRODUCT IN-DEPTH

REMANUFACTURED AIR STRUTS/SHOCKS

- ▲ Exact Fit & Functionality as OE
- ▲ Factory Active Damping & Ride
- ▲ Arnott Engineered to Improve Strut Longevity
- ▲ Plug & Play Installation Is Identical to OE

Arnott is the industry leader in remanufacturing used original equipment air suspension struts, amassing more than 25 years fine-tuning the process. Each month, Arnott purchases thousands of used cores that company engineers inspect to identify the most common failure points. Armed with this research, the Arnott R&D department develops superior designs, improving on those weak areas.

Arnott remanufactured struts reuse the original shock, top and bottom mounts, and any additional integral components helpful in maintaining full factory functionality. The core strut's shock is dyno tested on a computerized testing machine.

If the shock does not pass, it is not used. Arnott then conducts a deep cleaning, sands off rust, and repaints the strut with corrosion-resistant paint. Many of Arnott's remanufactured struts are also recharged.

Arnott then rebuilds each Air Strut by hand with new, longer-lasting seals; a multi-ply premium brand air bladder; heavy-duty crimping rings; new connectors, VOSS air fittings, and protective coverings including dust baffles and aluminium cans.

By reusing the OE shock, Arnott's remanufactured Air Struts maintain OE active damping functionality. All of Arnott's remanufactured parts are backed by the company's renowned Superior Warranties.



ARNOTT OFFERS REMANUFACTURED AIR STRUTS FOR

Audi • Bentley • BMW • Cadillac • GM • Land Rover
Maybach • Mercedes-Benz • Porsche/Volkswagen

| Year | Sub-Model Information | Air Springs | | New Air Struts/Shocks | | Remanufactured OE Struts/Shocks | | Coil Spring Conversion Kits | Air Suspension Compressors |
|--|-----------------------|-------------|------|-----------------------|------|---------------------------------|------|-----------------------------|----------------------------|
| | | FRONT | REAR | FRONT | REAR | FRONT | REAR | | |
| 57 & 62 | | | | | | | | | |
| <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2002-2012 | Base & S Models | | | | | RT AS-2746 | | | P-2192 |
| | | | | | | LT AS-2747 | | | |

LT Left RT Right



ARNOTT NEW AIR STRUT: AS-2792

- Fits GL-Class X164 and ML-Class W164 with ADS
- New Custom-Valved Shock Absorber
- Multi-Ply ContiTech Air Spring Bladder
- Pre-Assembled for Easy Installation
- Includes Detailed Installation Manual
- Designed & Assembled in the USA



| Year | Sub-Model Information | Air Springs | | New Air Struts/Shocks | | Remanufactured OE Struts/Shocks | | Coil Spring Conversion Kits | Air Suspension Compressors |
|---|---|-------------|------|-----------------------|------------|---------------------------------|------------|-----------------------------|----------------------------|
| | | FRONT | REAR | FRONT | REAR | FRONT | REAR | | |
| CL-CLASS <i>See footnotes for additional part information</i> | | | | | | | | | |
| 1999-2006 | W215 w/ABC, Incl. AMG To VIN #032099 | | | RT SK-2454 | RT SK-2456 | | | | |
| | W215 w/ABC, AMG From VIN #032562 | | | LT SK-2455 | LT SK-2457 | | | | |
| | W215 w/ABC, Excl. AMG, From VIN #032100 | | | RT SK-2458 | RT SK-2460 | | | | |
| | | | | LT SK-2459 | LT SK-2461 | | | | |
| 2006-2014 | W216 w/AIRMATIC, w/4MATIC | | | RT AS-2852 | RT AS-2821 | RT AS-2547 | RT AS-2603 | | P-2593 |
| | | | | LT AS-2853 | LT AS-2822 | LT AS-2548 | LT AS-2604 | | |
| | W216 w/ABC, AMG | | | RT SK-2553 | RT SK-2555 | | | | |
| | | | | LT SK-2554 | LT SK-2556 | | | | |
| | W216 w/ABC, Excl. AMG | | | RT SK-2549 | RT SK-2551 | | | | |
| | | | | LT SK-2550 | LT SK-2552 | | | | |

LT Left RT Right

COIL SPRING CONVERSION KIT: C-2896

- Converts E-Class W211 with Rear Air Suspension Only
- Powder-Coated Steel Springs
- Fits Without Modifications
- Detailed Installation Manual Available
- Not Applicable for Elegance Models
- Superior Warranties



| Year | Sub-Model Information | Air Springs | | New Air Struts/Shocks | | Remanufactured OE Struts/Shocks | | Coil Spring Conversion Kits | Air Suspension Compressors |
|--|---|--------------|--------------|-----------------------|---------------|---------------------------------|-----------|-----------------------------|----------------------------|
| | | FRONT | REAR | FRONT | REAR | FRONT | REAR | | |
| CLS-CLASS <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2004-2011 | W219 CLS55 & CLS63, AMG | | A-2725 34 RT | AS-2787 | | RT AS-2300 | | C-2278 3 25 | P-2192 |
| | | | | LT AS-2788 | | LT AS-2301 | | | P-3116 10 30 |
| | W219 w/AIRMATIC Only | | A-2724 34 RT | AS-2785 | SK-3039 30 RT | AS-2246 | | C-2278 3 25 | P-2192 |
| | | | | LT AS-2786 | | LT AS-2245 | | | P-3116 10 30 |
| | W219 w/AIRMATIC, w/ADS | | | | SK-3012 | | | | |
| 2012-2017 | W218 w/AIRMATIC, Incl. AMG | | RT A-2790 | | | | | C-3018 30 | P-2830 |
| | | | LT A-2791 | | | | | | |
| E-CLASS <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2002-2009 | W211 E55 & E63 AMG | | A-2725 34 RT | AS-2787 | SK-3039 30 RT | AS-2300 | | C-2278 3 25 | P-2192 |
| | | | | LT AS-2788 | | LT AS-2301 | | | P-3116 10 30 |
| | W211 w/4MATIC, Excl. AMG | | A-2724 34 RT | AS-3000 | SK-3039 30 RT | AS-2294 | | C-2663 30 | P-2192 |
| | | | | LT AS-3001 | | LT AS-2295 | | | P-3116 10 30 |
| | W211 w/o 4MATIC, Excl. AMG | | A-2724 34 RT | AS-2785 | SK-3039 30 RT | AS-2246 | | C-2278 3 25 | P-2192 |
| | | | | LT AS-2786 | | LT AS-2245 | | | P-3116 10 30 |
| | W211 w/ADS, w/AIRMATIC, w/4MATIC, Wagon | | A-2724 34 RT | AS-3000 | SK-3012 | RT AS-2294 | SK-3197 | C-3014 3 30 | P-2192 |
| | | | | LT AS-3001 | | LT AS-2295 | | | P-3116 10 30 |
| W211 w/AIRMATIC, w/o 4MATIC, Wagon | | A-2724 34 RT | AS-2785 | SK-3039 30 RT | AS-2246 | | | P-2192 | |
| | | | LT AS-2786 | | LT AS-2245 | | | P-3116 10 30 | |
| 2009-2017 | W211 w/Rear Levelling Only, Wagon, Incl. 4MATIC | | A-2726 34 | | SK-3039 30 | | | C-2896 5 38 | P-2192 |
| | | | | | | | | | P-3116 10 30 |
| W212 w/AIRMATIC, Incl. AMG | | RT A-2790 | AS-3034 30 | | | | C-3018 30 | P-2830 | |
| | | LT A-2791 | | | | | | | |

- 3 Complete 4-Wheel Kit
- 5 Rear Only
- 10 Remanufactured Air Suspension Compressor
- 25 Includes Shocks
- 30 Coming Soon
- 34 Must be Replaced in Pairs
- 38 Not Applicable For Elegance Models

LT Left RT Right

ARNOTT NEW AIR SPRING: A-2724

- Arnott-Designed Rear Air Spring Installs Over 90% Faster than OE
- Designed to Provide an Excellent Ride without the OE Reservoir
- Lasts Longer with Durable ContiTech Air Bladder & Dust Boot Cover
- New Airline Fitting and Upper Retaining Pin for OE Fit
- Detailed Installation Manual Available Online



ARNOTT REMANUFACTURED ABC STRUT: SK-2471

- Hydropneumatic Struts for SL-Class R230 without AMG
- Tested, Disassembled and Rebuilt from the Ground Up
- A Nearly Indestructible Polyurethane Seal
- Remanufactured in the USA
- Superior Warranties



| Year | Sub-Model Information | Air Springs | | New Air Struts/Shocks | | Remanufactured OE Struts/Shocks | | Coil Spring Conversion Kits | Air Suspension Compressors |
|--|-----------------------------------|----------------------|--------|-----------------------|---------|--|--|-----------------------------|----------------------------|
| | | FRONT | REAR | FRONT | REAR | FRONT | REAR | | |
| GL-CLASS <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2006-2012 | X164 w/ADS (GL63 AMG Only) | A-2575 ²⁴ | A-2596 | AS-3089 | | AS-2463 | | C-2584 ³⁰ | P-3072 |
| | X164, w/ADS | A-2575 ²⁴ | A-2596 | AS-2792 | SK-2867 | AS-2450 | | C-2584 ³⁰ | P-3072 |
| | X164, w/o ADS | A-2575 ²⁴ | A-2596 | AS-3005 | SK-2868 | | | C-2584 ³⁰ | |
| 2012-2016 | X166 w/o ADS (incl. GL63 AMG) | | A-2596 | | | RT AS-3085 LT AS-3086 | | | P-2858 |
| | X166 w/ADS, w/o AMG | | A-2596 | | | RT AS-3060 LT AS-3061 | | | P-2858 |
| | | | | | | | | | |
| ML-CLASS <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2005-2011 | W164 w/AIRMATIC, w/ADS, Excl. AMG | A-2575 ²⁴ | A-2596 | AS-2792 | SK-2867 | AS-2450 | | | P-3214 |
| 2006-2011 | W164 ML63 AMG Only | A-2575 ²⁴ | A-2596 | AS-2802 | | AS-2463 | | | P-3214 |
| 2011-2015 | W166 Incl. ML63 AMG | | A-2596 | | | | | | |
| R-CLASS <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2006-2013 | W251 Rear Only | | A-2597 | | | | | | P-2618 |
| | W251 w/4-Corner | A-2587 ²⁴ | A-2597 | AS-2833 | | AS-2394 | | | P-3215 |
| SL-CLASS <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2003-2006 | R230 Excl. AMG | | | | | RT SK-2412 LT SK-2413 | RT SK-2414 LT SK-2415 | C-3042 ³⁰ | |
| | R230 SL55 & SL65 AMG | | | | | RT SK-2417 LT SK-2418 | RT SK-2419 LT SK-2420 | C-3042 ³⁰ | |
| | R230 Excl. AMG | | | | | RT SK-2470 LT SK-2471 | RT SK-2472 LT SK-2473 | C-3042 ³⁰ | |
| 2007-2012 | R230 SL63 & SL65 AMG | | | | | RT SK-2482 LT SK-2483 | RT SK-2484 LT SK-2485 | C-3042 ³⁰ | |
| | R231 SL550 | | | | | RT SK-3044 ³⁰ LT SK-3045 ³⁰ | RT SK-3046 ³⁰ LT SK-3047 ³⁰ | | |
| V-CLASS <i>See footnotes for additional part information</i> | | | | | | | | | |
| 1996-2003 | W638 | | A-2799 | | | | | | P-2219 |
| 2004-2014 | W639 | | A-2801 | | | | | | P-2800 |

²⁴ New Air Spring Only, Reuse Factory Shock ³⁰ Coming Soon

LT Left RT Right

| Year | Sub-Model Information | Air Springs | | New Air Struts/Shocks | | Remanufactured OE Struts/Shocks | | Coil Spring Conversion Kits | Air Suspension Compressors |
|---|---|-------------|------|--------------------------|--------------------------|---------------------------------|--------------------------|-----------------------------------|----------------------------|
| | | FRONT | REAR | FRONT | REAR | FRONT | REAR | | |
| S-CLASS <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2000-2006 | W220 w/ABC, To VIN #290213 | | | | | RT SK-2454 LT SK-2455 | | | |
| | W220 w/ABC, From VIN #290214 | | | | | | RT SK-2456 LT SK-2457 | | |
| | W220 w/ABC, From VIN #372602 | | | | | RT SK-2458 LT SK-2459 | RT SK-2460 LT SK-2461 | | |
| | W220 w/ABC, Excl. AMG, To VIN #290213 | | | | | RT SK-2454 LT SK-2455 | | | |
| | W220 w/ABC, Excl. AMG, From VIN #290214 | | | | | RT SK-2422 LT SK-2423 | RT SK-2456 LT SK-2457 | | |
| 2003-2006 | W220 w/AIRMATIC, w/o 4MATIC | | | AS-2605 | AS-2884 | AS-2193 | AS-2194 | C-2242 ³ ²⁵ | P-2192 |
| | W220 w/AIRMATIC, w/4MATIC | | | RT AS-2783 LT AS-2784 | AS-2884 | | AS-2194 | C-2271 ³ ²⁵ | P-2192 |
| 2007-2013 | W221 w/ABC, AMG | | | | | RT SK-2553 LT SK-2554 | RT SK-2555 LT SK-2556 | | |
| | W221 w/ABC, Excl. AMG | | | | | RT SK-2549 LT SK-2550 | RT SK-2551 LT SK-2552 | | |
| | W221 w/AIRMATIC, w/4MATIC | | | RT AS-2852 LT AS-2853 | RT AS-2821 LT AS-2822 | RT AS-2547 LT AS-2548 | RT AS-2603 LT AS-2604 | | P-2593 |
| | W221 w/AIRMATIC, w/o 4MATIC | | | AS-2820 | RT AS-2821 LT AS-2822 | AS-2540 | RT AS-2603 LT AS-2604 | C-2609 ³ ³⁰ | P-2593 |

³ Complete 4-Wheel Kit ³⁰ Coming Soon
²⁵ Includes Shocks

LT Left RT Right

PRODUCTS FOR
PEUGEOT

[re]vive your ride
with new Arnott air struts



Ask for Arnott.

AIR SUSPENSION COMPRESSOR: P-2851

- New OES Air Suspension Compressor for Peugeot Expert
- Compatible with OE Air Lines
- Relay Included
- Installation Manual Available
- Superior Warranties



| Year | Sub-Model Information | Air Springs | | New Air Struts/Shocks | | Remanufactured OE Struts/Shocks | | Coil Spring Conversion Kits | Air Suspension Compressors |
|---------------------|-----------------------|-------------|------|-----------------------|------|---------------------------------|------|-----------------------------|----------------------------|
| | | FRONT | REAR | FRONT | REAR | FRONT | REAR | | |
| EXPERT 2007-2011 | | | | | | | | | P-2851 |

PRODUCTS FOR
PORSCHE/VW



ARNOTT NEW AIR SPRING: A-2572

- New Front Left Air Spring fits Audi Q7, Porsche Cayenne and VW Touareg
- Easy-to-Install Economical Design
- Includes New Rubber Upper Mount & Hardware
- CNC-Machined Components
- Continental Air Spring Bladder



| Year | Sub-Model Information | Air Springs | | New Air Struts/Shocks | | Remanufactured OE Struts/Shocks | | Coil Spring Conversion Kits | Air Suspension Compressors |
|--|-----------------------|------------------------|-----------|--------------------------------|------|---------------------------------|--------------------------------|-----------------------------|----------------------------|
| | | FRONT | REAR | FRONT | REAR | FRONT | REAR | | |
| PORSCHE CAYENNE <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2002-2010 | w/Air Suspension | RT A-2571 LT A-2572 | A-2523 | | | | | C-2616 3 25 31 35 | P-2496 |
| 2011-2017 | 92A Chassis | | | | | RT AS-3056 30 LT AS-3057 30 | RT AS-3058 30 LT AS-3059 30 | | |
| PORSCHE PANAMERA <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2010-2016 | 970 Chassis | | A-3024 30 | RT AS-3037 30 LT AS-3038 30 | | RT AS-3035 30 LT AS-3036 30 | | | |
| VOLKSWAGEN PHAETON <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2002-2006 | 4,2 & 6,0 Litre | | | RT AS-2892 LT AS-2893 | | RT AS-2580 LT AS-2581 | | | P-2740 |
| VOLKSWAGEN TOUAREG <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2002-2010 | w/Air Suspension | RT A-2571 LT A-2572 | A-2523 | | | | | C-2616 3 25 31 35 | P-2496 |

3 Complete 4-Wheel Kit 30 Coming Soon 35 Gas Engines Only
 25 Includes Shocks 31 All, w/Air Suspension, w/o PDCC
 LT Left RT Right

PRODUCTS FOR TOYOTA/LEXUS

ARNOTT NEW AIR STRUT: AS-2855

- New Custom-Valved Shock Absorber Provides a Great Ride for the LS 460/Toyota Celsior
- Rugged Multi-Ply ContiTech Air Spring Bladder
- Strut is Protected By Aluminum Can & Dust Boot Cover
- Arnott-Designed to Fit Left or Right Side
- Designed & Assembled in the USA



PRODUCT IN-DEPTH

OES AIR SUSPENSION COMPRESSORS



- ▲ Tested by Arnott to Assure a Long Life & Reduced Failure Rates
- ▲ Most Include Air Lines, Wiring Harnesses & Relays for Faster Installs
- ▲ Superior Warranties

Compressor burnout is one of the more frequent air suspension problems encountered by drivers. Burnout occurs when the air suspension compressor becomes inoperative because of overuse caused by a leaking air spring or other component. By establishing partnerships with the leading Original Equipment Suppliers of Air Suspension Compressors such as WABCO, Arnott provides direct replacements for these critical components. These high-quality compressors are tested in Arnott's facilities and then fitted with application-specific components to provide a fast, flawless, Plug & Play installation.

Unlike some compressors simply modified to fit a vehicle, a growing number of Arnott-supplied compressors are the identical, application specific parts designed by WABCO.

These pumps incorporate high-level integration mechatronics and are high-performance, yet quiet air compressors with maintenance-free integrated air dryers. WABCO compressors from Arnott come completely assembled from the factory in Germany with application-specific air lines, wiring harness, and brackets. These direct replacement compressors even come in a WABCO box and are ready to install with included application-specific mounting hardware and relay.

Air Suspension Compressors from Arnott come with a Superior Warranty against manufacturer's defects. They are fully covered if they haven't been subjected to burnout from leaking air suspension components, modified, or missing labels and plugs.

ARNOTT OFFERS OES AIR SUSPENSION COMPRESSORS FOR

Audi • Bentley • BMW • Cadillac • Citroën • Ford • GM • Jaguar • Land Rover • Lincoln
Maybach • Mercury • Mercedes-Benz • Peugeot • Porsche/Volkswagen • Toyota/Lexus

| Year | Sub-Model Information | Air Springs | | New Air Struts/Shocks | | Remanufactured OE Struts/Shocks | | Coil Spring Conversion Kits | Air Suspension Compressors |
|--|-----------------------|-------------|--------|-----------------------|-----------------------|---------------------------------|------|-----------------------------|--------------------------------|
| | | FRONT | REAR | FRONT | REAR | FRONT | REAR | | |
| GX 460 <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2010-2017 | J150 Chassis | | | | | | | | P-3191 |
| LAND CRUISER PRADO / GX 470 <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2001-2009 | J120 Chassis | | A-2949 | SK-2812 | SK-2813 | | | C-2410 ⁵ | P-3192 P-3186 ⁸⁰ |
| LS 430 <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2000-2006 | XF30 Chassis | | | AS-2894 | AS-2895 ⁸⁰ | | | C-3011 ⁸⁰ | P-3187 |
| CELSIOR / LS 460 <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2006-2017 | USF 40/41 Chassis | | | AS-2855 | AS-2856 ⁸⁰ | | | | P-3188 |
| LS 600H L <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2008-2016 | | | | AS-2855 | AS-2856 ⁸⁰ | | | | P-3188 |
| RX 450H <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2011-2015 | AL10 Chassis | | | | | | | | P-3194 |
| SEQUOIA <i>See footnotes for additional part information</i> | | | | | | | | | |
| 2005-2007 | 1st Gen. Chassis | | | | | | | | P-3190 |
| 2008-2017 | 2nd Gen. Chassis | | | | | | | | P-3189 |

⁵ Rear Only
⁸⁰ Coming Soon

PRODUCT FEATURES

ARNOTT-DESIGNED NEW AIR STRUTS

- ▲ Custom-Valved Shock Absorber Provides Fantastic Ride
- ▲ Premium Brand Air Sleeve, Bump Stop & Dust Boot
- ▲ Works With Vehicle's Auto Leveling Functionality
- ▲ CNC-Machined Aluminium Top
- ▲ Improved Seals Prevent Leaks
- ▲ Connects to ADS System with no Modifications
- ▲ Engineered & Assembled in the USA
- ▲ Superior Warranties



OE QUALITY FIT EVERY TIME!
SUPERIOR WARRANTIES
DETAILED INSTRUCTIONS AVAILABLE ONLINE

REMANUFACTURED AIR STRUTS

- ▲ Tested, Cleaned & Recharged OE Shock Absorber
- ▲ New Sealing Cap & Air Line Fitting
- ▲ Works With Vehicle's Auto Damping & Leveling
- ▲ Premium Brand Air Sleeve, Bump Stop & Dust Boot
- ▲ OE Top Mount & Sensor
- ▲ Remanufactured in the USA
- ▲ Superior Warranties



AIR SPRINGS



- ▲ Premium Brand Air Sleeve
- ▲ High-Grade Crimping Rings
- ▲ Engineered & Assembled in the USA & the European Union
- ▲ OE Air Line Compatible, No Modifications Necessary
- ▲ High-Impact Resin or Aircraft-Quality Aluminium
- ▲ Superior Warranties

AIR SUSPENSION COMPRESSORS



- ▲ New OES Quality Compressors
- ▲ Life-Cycle Tested
- ▲ Epoxy-Electrocoated Finish to Prevent Corrosion
- ▲ Manufactured With RoHS-Compliant Materials
- ▲ Most Compatible With OE Lines And Plugs
- ▲ Superior Warranties

COIL SPRING CONVERSION KITS



- ▲ Electronic Bypass Module (EBM) Eliminates Fault Codes
- ▲ Custom-Valved Shock Absorbers
- ▲ Durable American-Made, Powder-Coated Coil Springs
- ▲ Pre-Assembled For Easy & Safe Installation
- ▲ OE Fit With No Modifications Needed
- ▲ Superior Warranties

The car must be supported by a jack when inflating the air bag. If this is not done, the air spring is folded underneath the car, causing the air spring to set incorrectly.



When replacing the air spring, the shock should also been checked. If the shock leaks oil, the oil can leak into the air spring causing it to wear out.

The relay of the compressor must be changed. If not, there is a huge chance that the relay will be 'stuck' causing the compressor to continuously pump air. This will eventually lead to a burned out compressor.



Usually you do not need to tighten the Voss connector. When you decide to do so, it can damage the screw thread and the air spring can start leaking on this connection.

| Arnott Item # | OEM # | | | | | | | | | |
|----------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|------------|-------------|
| AUDI | | | | | | | | | | |
| A-2133 | 4Z7616052A | 4Z7616051A | | | | | | | | |
| A-2523 | 95535850332 | 7L6616503B | 7L8616503B | 95535850331 | 95535850330 | 95535850321 | 95535850300 | 7L6616503A | 7L6616503 | |
| A-2571 | 95535840431 | 95535840421 | 7L6616404B | 7L8616404B | 7L5616404E | 95535840410 | 95535840400 | 7L6616404A | 7L8616404A | 95535840430 |
| | 95535840420 | 7L8616404 | 7L6616405 | | | | | | | |
| A-2572 | 95535840331 | 95535840321 | 7L6616403B | 7L8616403B | 7L5616403E | 95535840310 | 95535840300 | 7L6616403A | 7L8616403A | 95535840330 |
| | 95535840320 | 7L8616403 | 7L6616403 | | | | | | | |
| A-2731 | 4Z7616052A | 4Z7616051A | | | | | | | | |
| A-2869 | 4Z7616051D | 4Z7616051B | | | | | | | | |
| A-2885 | 4Z7616051D | 4Z7616051B | | | | | | | | |
| A-2960 | 4F0616001 | 4F0616001J | | | | | | | | |
| AS-2560 | 4E0616040AF | 4E0616040AH | 4E0616040T | 4E0616040AB | 4E0616040R | | | | | |
| AS-2561 | 4E0616039AF | 4E0616039AH | 4E0616039T | 4E0616039AB | 4E0616039R | | | | | |
| AS-2562 | 4E0616040AJ | 4E0616040AK | 4E0616040AG | 4E0616040AA | 4E0616040AC | 4E0616040S | 4E0616040AE | | | |
| AS-2563 | 4E0616039AJ | 4E0616039AK | 4E0616039AG | 4E0616039AA | 4E0616039AC | 4E0616039S | 4E0616039AE | | | |
| AS-2775 | 4E0616040AF | 4E0616040AH | 4E0616040T | 4E0616040AB | 4E0616040R | | | | | |
| AS-2776 | 4E0616039AF | 4E0616039AH | 4E0616039T | 4E0616039AB | 4E0616039R | | | | | |
| AS-2777 | 4E0616040AJ | 4E0616040AK | 4E0616040AG | 4E0616040AA | 4E0616040AC | 4E0616040S | 4E0616040AE | | | |
| AS-2778 | 4E0616039AJ | 4E0616039AK | 4E0616039AG | 4E0616039AA | 4E0616039AC | 4E0616039S | 4E0616039AE | | | |
| AS-2816 | 4F0616040AA | 4F0616040S | 4F0616040T | 4F0616040R | 4F0616040Q | 4F0616040P | 4F0616040N | 4F0616040M | 4F0616040J | |
| AS-2817 | 4F0616039AA | 4F0616039S | 4F0616039T | 4F0616039R | 4F0616039H | 4F0616039P | 4F0616039N | 4F0616039M | 4F0616039J | |
| | 4H0616039T | 4H0616039G | 4H0616039F | 4H0616039E | 4H0616039H | 4H6616039E | 4H6616039F | 4H6616039G | 4H6616039H | 4G0616039L |
| AS-2864 | 4G0616039N | 4G0616039AD | 4H0616039R | 4H0616039M | 4H0616039P | 4H0616039AB | 4H0616039AD | 4H0616039AK | | |
| AS-2865 | 4H0616039AA | 4H0616039AC | 4H0616039AE | 4H0616039AJ | 4H0616039J | 4H0616039S | 4H0616039AQ | | | |
| AS-2958 | 4E0616002N | 4E0616002Q | 4E0616002D | 4E0616002E | 4E0616002G | 4E0616002K | 4E0616002M | | | |
| AS-2959 | 4E0616001N | 4E0616001Q | 4E0616001D | 4E0616001E | 4E0616001G | 4E0616001M | 4E0616001K | | | |
| AS-2965 | 4E0616002A | 4E0616002F | 4E0616002H | 4E0616002L | 4E0616002P | | | | | |
| AS-2966 | 4E0616001A | 4E0616001F | 4E0616001H | 4E0616001L | 4E0616001P | | | | | |
| AS-3030 | 4E0616002D | 4E0616002E | 4E0616002G | 4E0616002K | 4E0616002M | 4E0616002N | 4E0616002Q | | | |
| AS-3031 | 4E0616001N | 4E0616001Q | 4E0616001D | 4E0616001E | 4E0616001G | 4E0616001M | 4E0616001K | | | |
| AS-3032 | 4E0616002A | 4E0616002F | 4E0616002H | 4E0616002L | 4E0616002P | | | | | |
| AS-3033 | 4E0616001A | 4E0616001F | 4E0616001H | 4E0616001L | 4E0616001P | | | | | |
| P-2134 | 4Z7616007A | | | | | | | | | |
| P-2496 | 4L0698007C | 7L0698853C | 95535890105 | 95535890104 | 4L0698007B | 4L0698007A | 4L0698007 | 7L0698853A | 7L0698853B | 7L8616006A |
| | 7L0698853 | 7L8616006C | 7L8616007A | 7L8616007C | 7L8616007E | 7L8616007F | 95535890103 | 95535890102 | | |
| P-2539 | 4E0616007D | 4E0616007B | 4E0616007 | 4E0616005F | 4E0616005D | 4E0616005H | | | | |
| P-2599 | 4E0616007C | 4E0616007E | 4E0616007A | 4E0616005E | 4E0616005G | | | | | |
| P-2984 | 4F0616005F | 4F0616005E | 4F0616006A | 4F0616006 | 4F0616007 | | | | | |
| P-2986 | 4H0616005A | 4H0616005B | 4H0616005C | 4H0616005D | | | | | | |
| SK-2779 | 4Z7413031A | 4Z7413031 | 4Z7413032 | | | | | | | |
| SK-2805 | 4Z7513031 | 4Z7513031A | 4Z7513032 | 4Z7513032A | | | | | | |
| BENTLEY | | | | | | | | | | |
| AS-2580 | 3D0616040AC | 3D0616040AD | 3D0616040N | 3W0616040 | 3W5616040 | 3W7616040 | 3D0616040 | 3D5616040 | 3D7616040 | 3D0616040AA |
| | 3D0616040AB | 3D0616040S | 3D0616040L | 3D0616040T | 3D0616040M | 3D0616040Q | 3D0616001H | 3D0616002J | 3D0616039Q | 3D0616039P |
| | 3D0616040P | 3D0616040G | | | | | | | | |
| | 3D0616039AD | 3D0616039N | 3D0616039AC | 3W0616039 | 3W5616039 | 3W7616039 | 3D0616039 | 3D5616039 | 3D7616039 | 3D0616039AA |
| AS-2581 | 3D0616039AB | 3D0616039S | 3D0616039L | 3D0616039T | 3D0616039M | 3D0616039Q | 3D0616039P | 3D0616040Q | 3D0616040P | 3D0616001H |
| | 3D0616002J | 3D0616039G | | | | | | | | |
| | 3D0616040AC | 3D0616040AD | 3D0616040N | 3D0616040 | 35616040 | 37616040 | 3D0616040 | 3D5616040 | 3D7616040 | 3D0616040AA |
| AS-2892 | 3D0616040AB | 3D0616040S | 3D0616040 | 3D0616040T | 3D0616040M | 3D0616040Q | 3D0616001 | 3D0616002J | 3D0616039Q | 3D0616039P |
| | 3D0616040P | 3D0616040G | | | | | | | | |

| Arnott Item # | OEM # | | | | | | | | | |
|-----------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|
| BENTLEY | | | | | | | | | | |
| | 3D0616039AD | 3D0616039N | 3D0616039AC | 30616039 | 35616039 | 37616039 | 3D0616039 | 3D5616039 | 3D7616039 | 3D0616039AA |
| AS-2893 | 3D0616039AB | 3D0616039S | 3D0616039 | 3D0616039T | 3D0616039M | 3D0616039Q | 3D0616039P | 3D0616040Q | 3D0616040P | 3D0616001 |
| | 3D0616002J | 3D0616039G | | | | | | | | |
| AS-2968 | 3W0616002 | 3W0616002E | 3W5616002 | 3W5616002A | 3W5616002C | 3W5616002D | 3W7616002 | 3W7616002A | 3W7616002E | 3W7616002C |
| | 3W8616002 | | | | | | | | | |
| AS-2969 | W0616001 | 3W0616001E | 3W5616001 | 3W5616001A | 3W5616001C | 3W5616001D | 3W7616001 | 3W7616001A | 3W7616001E | 3W7616001C |
| | 3W8616001 | | | | | | | | | |
| P-2740 | 3D0616005P | 3D0616005L | 3D0616005M | 3D0616007C | 3D0616007D | 3D0616007E | 3D0616005H | 3D0616005K | | |
| BMW | | | | | | | | | | |
| A-2501 | 37121095580 | | | | | | | | | |
| A-2502 | 37121095579 | | | | | | | | | |
| A-2503 | 37126750356 | | | | | | | | | |
| A-2504 | 37126750355 | | | | | | | | | |
| A-2642 | 37126790078 | 37126790079 | 37126790080 | 37126790081 | 37126790082 | 37126790083 | 37126783419 | 37126783420 | 37126773664 | 37126774041 |
| | 37126776995 | | | | | | | | | |
| A-2737 | 37121094613 | 37121095081 | | | | | | | | |
| A-2738 | 37121094614 | 37121095082 | | | | | | | | |
| A-2755 | 37126765602 | 37126765603 | | | | | | | | |
| A-2780 | 37106781843 | 37106781844 | 37106781827 | 37106781828 | 37106784378 | 37106784379 | 37106784380 | 37106784381 | | |
| A-2861 | 37116757502 | 37116761444 | | | | | | | | |
| A-2862 | 37116757501 | 37116761443 | | | | | | | | |
| AS-2305 | 37116757502 | 37116761444 | | | | | | | | |
| AS-2306 | 37116757501 | 37116761443 | | | | | | | | |
| AS-2764 | 37116761444 | 37116757502 | | | | | | | | |
| AS-2765 | 37116761443 | 37116757501 | | | | | | | | |
| AS-2978 | 37126785536 | 37106778798 | 37126758582 | 37126767128 | 37126758580 | | | | | |
| AS-2979 | 37126785535 | 37106778797 | 37126758581 | 37126767127 | 37126758579 | | | | | |
| AS-2980 | 37126785538 | 37106778800 | 37106767864 | 37126758574 | | | | | | |
| AS-2981 | 37126785537 | 37106778799 | 37106767863 | 37126758573 | | | | | | |
| K-2897 | 37206789937 | 37206789938 | | | | | | | | |
| K-2898 | 37206789937 | 37206789938 | | | | | | | | |
| P-2469 | 37226787616 | 37226778773 | 37221092349 | | | | | | | |
| P-2494 | 37226787617 | 37226753862 | 37226779712 | 37220151015 | | | | | | |
| P-2985 | 37206789450 | 37206864215 | 37206794465 | 37206789165 | 37206784137 | | | | | |
| P-3220 | 37106793778 | 37206792855 | 37106789937 | | | | | | | |
| P-3221 | 37206859714 | 37206799419 | 37206789938 | 37226775479 | 37226785506 | | | | | |
| BUICK | | | | | | | | | | |
| A-2610 | 25815604 | 15125532 | 15276029 | 15183661 | 15183657 | 15159630 | 15090620 | 15089028 | | |
| AS-2190 | 19299843 | 19257784 | | | | | | | | |
| AS-2950 | 19302768 | 15211375 | 19302769 | 15211376 | | | | | | |
| P-2857 | 25978169 | 25878674 | 25789710 | 15006679 | 15145230 | 15187099 | 15094346 | | | |
| P-2982 | 20827740 | 20794301 | 25994396 | 25806015 | 15811960 | | | | | |
| SK-2189 | 22064764 | | | | | | | | | |
| SK-2952 | 19300024 | 15211374 | | | | | | | | |
| CADILLAC | | | | | | | | | | |
| AS-2121 | 22064872 | 22064873 | | | | | | | | |
| AS-2125 | 22064565 | | | | | | | | | |
| AS-2163 | 22400526 | | | | | | | | | |
| AS-2177 | 22064727 | | | | | | | | | |
| AS-2185 | 19299843 | 19257784 | | | | | | | | |
| AS-2190 | 19299843 | 19257784 | | | | | | | | |
| | 19300045 | 19300046 | 22187156 | 15869656 | 15945872 | 19300069 | 19300071 | 19300072 | 25885469 | 25979391 |
| AS-2700 | 25979393 | 25979394 | 15756926 | 19300040 | 22187152 | 88965458 | 88965338 | 22400885 | 22187158 | 25885470 |
| | 15924688 | 15869658 | 25885467 | 15918525 | 15852159 | | | | | |
| | 19300045 | 19300046 | 22187156 | 15869656 | 15945872 | 19300069 | 19300071 | 19300072 | 25885469 | 25979391 |
| AS-2708 | 25979393 | 25979394 | 15756926 | 19300040 | 22187152 | 88965458 | 88965338 | 22400885 | 22187158 | 25885470 |
| | 15924688 | 15869658 | 25885467 | 15918525 | 15852159 | | | | | |
| | 19300045 | 19300046 | 22187156 | 15869656 | 15945872 | 19300069 | 19300071 | 19300072 | 25885469 | 25979391 |
| AS-2715 | 25979393 | 25979394 | 15756926 | 19300040 | 22187152 | 88965458 | 88965338 | 22400885 | 22187158 | 25885470 |
| | 15924688 | 15869658 | 25885467 | 15918525 | 15852159 | | | | | |
| AS-2950 | 19302768 | 15211375 | 19302769 | 15211376 | | | | | | |

| Arnott Item # | OEM # | | | | | | | | | |
|------------------|------------|------------|-----------|------------|----------|---------------|---------------|----------|----------|----------|
| CADILLAC | | | | | | | | | | |
| AS-3066 | 23290661 | | | | | | | | | |
| | 15254590 | 20930288 | 22941806 | 15070878 | 15056494 | 10395825 | 15101577 | 20837299 | 25913289 | 15949881 |
| P-2793 | 15296756 | 19299545 | | | | | | | | |
| P-2982 | 20827740 | 20794301 | 25994396 | 25806015 | 15811960 | | | | | |
| SK-2111 | 15147082 | 15219513 | | | | | | | | |
| SK-2118 | N/A | | | | | | | | | |
| SK-2162 | N/A | | | | | | | | | |
| SK-2176 | 22064595 | 22064594 | | | | | | | | |
| SK-2178 | 22064728 | 22064729 | | | | | | | | |
| SK-2183 | 22064724 | 22064723 | | | | | | | | |
| SK-2186 | 22064766 | 22064765 | | | | | | | | |
| SK-2189 | 22064764 | | | | | | | | | |
| SK-2264 | N/A | | | | | | | | | |
| SK-2760 | 22187159 | 22187157 | 22187155 | 22400248 | 22187151 | 88965339 | 22400884 | 19300047 | | |
| SK-2806 | 19209555 | 20810270 | | | | | | | | |
| SK-2814 | 22187159 | | | | | | | | | |
| SK-2952 | 19300024 | 15211374 | | | | | | | | |
| | 19209555 | 20810270 | 25888675 | 25845447 | 25888683 | 25845438 | 25845446 | 25888684 | 15939374 | 15911938 |
| SK-2954 | 15918522 | 15909491 | 15886465 | 19300031 | 19353945 | | | | | |
| CHEVROLET | | | | | | | | | | |
| A-2610 | 25815604 | 15125532 | 15276029 | 15183661 | 15183657 | 15159630 | 15090620 | 15089028 | | |
| AS-2235 | 22064811 | 19169325 | 88946637 | | | | | | | |
| | 19300045 | 19300046 | 22187156 | 15869656 | 15945872 | 19300069 | 19300071 | 19300072 | 25885469 | 25979391 |
| AS-2700 | 25979393 | 25979394 | 15756926 | 19300040 | 22187152 | 88965458 | 88965338 | 22400885 | 22187158 | 25885470 |
| | 15924688 | 15869658 | 25885467 | 15918525 | 15852159 | | | | | |
| | 19300045 | 19300046 | 22187156 | 15869656 | 15945872 | 19300069 | 19300071 | 19300072 | 25885469 | 25979391 |
| AS-2708 | 25979393 | 25979394 | 15756926 | 19300040 | 22187152 | 88965458 | 88965338 | 22400885 | 22187158 | 25885470 |
| | 15924688 | 15869658 | 25885467 | 15918525 | 15852159 | | | | | |
| | 19300045 | 19300046 | 22187156 | 15869656 | 15945872 | 19300069 | 19300071 | 19300072 | 25885469 | 25979391 |
| AS-2715 | 25979393 | 25979394 | 15756926 | 19300040 | 22187152 | 88965458 | 88965338 | 22400885 | 22187158 | 25885470 |
| | 15924688 | 15869658 | 25885467 | 15918525 | 15852159 | | | | | |
| AS-3066 | 23290661 | | | | | | | | | |
| | 15254590 | 20930288 | 22941806 | 15070878 | 15056494 | 10395825 | 15101577 | 20837299 | 25913289 | 15949881 |
| P-2793 | 15296756 | 19299545 | | | | | | | | |
| SK-2760 | 22187159 | 22187157 | 22187155 | 22400248 | 22187151 | 88965339 | 22400884 | 19300047 | | |
| SK-2806 | 19209555 | 20810270 | | | | | | | | |
| SK-2814 | 22187159 | | | | | | | | | |
| | 19209555 | 20810270 | 25888675 | 25845447 | 25888683 | 25845438 | 25845446 | 25888684 | 15939374 | 15911938 |
| SK-2954 | 15918522 | 15909491 | 15886465 | 19300031 | 19353945 | | | | | |
| CITROËN | | | | | | | | | | |
| A-2938 | | | | | | | | | | |
| A-2939 | 5102GN | 5102R8 | | | | | | | | |
| P-2851 | 9677839180 | 5277P8 | 5277G5 | | | | | | | |
| P-2854 | 9801906980 | 9682022980 | 415404830 | 4154030030 | 5277E5 | 9682022980-00 | 0354154048300 | | | |
| GMC | | | | | | | | | | |
| A-2610 | 25815604 | 15125532 | 15276029 | 15183661 | 15183657 | 15159630 | 15090620 | 15089028 | | |
| | 19300045 | 19300046 | 22187156 | 15869656 | 15945872 | 19300069 | 19300071 | 19300072 | 25885469 | 25979391 |
| AS-2700 | 25979393 | 25979394 | 15756926 | 19300040 | 22187152 | 88965458 | 88965338 | 22400885 | 22187158 | 25885470 |
| | 15924688 | 15869658 | 25885467 | 15918525 | 15852159 | | | | | |
| | 19300045 | 19300046 | 22187156 | 15869656 | 15945872 | 19300069 | 19300071 | 19300072 | 25885469 | 25979391 |
| AS-2708 | 25979393 | 25979394 | 15756926 | 19300040 | 22187152 | 88965458 | 88965338 | 22400885 | 22187158 | 25885470 |
| | 15924688 | 15869658 | 25885467 | 15918525 | 15852159 | | | | | |

| Arnott Item # | OEM # | | | | | | | | | |
|-------------------|-------------|------------|------------|------------|-------------|-------------|-------------|-----------|-----------|-----------|
| GMC | | | | | | | | | | |
| SK-2806 | 19209555 | 20810270 | | | | | | | | |
| SK-2814 | 22187159 | | | | | | | | | |
| SK-2954 | 19209555 | 20810270 | 25888675 | 25845447 | 25888683 | 25845438 | 25845446 | 25888684 | 15939374 | 15911938 |
| | 15918522 | 15909491 | 15886465 | 19300031 | 19353945 | | | | | |
| FORD | | | | | | | | | | |
| A-2105 | 3U2Z5580PA | 3U2Z5580BA | 6W1Z5560AA | 3U2Z5580AA | FOVY5560A | | | | | |
| A-2143 | 6L1Z3C199AA | | | | | | | | | |
| A-2148 | 3U2Z5580KA | | | | | | | | | |
| A-2153 | 3U2Z5580LA | | | | | | | | | |
| A-2220 | 3U2Z5580PA | 3U2Z5580BA | 6W1Z5560AA | 3U2Z5580AA | FOVY5560A | | | | | |
| A-2647 | 8L1Z5A891B | 7L1Z5A891B | | | | | | | | |
| A-2735 | 4L1Z5A891AA | | | | | | | | | |
| P-2932 | 1L1Z5319AA | 1L1Z5319BA | 6L1Z5319AA | | | | | | | |
| P-2936 | F6AZ5319AA | 8W1Z5319A | F1VY5319A | | | | | | | |
| P-2937 | 7L1Z5319AE | | | | | | | | | |
| SK-2723 | AU2Z18124D | AU2Z18124H | AU2Z18124C | AU2Z18124G | 6L7Z18124AD | 6L7Z18124BC | 5L1Z18125AA | | | |
| JAGUAR | | | | | | | | | | |
| AS-2888 | C2C41349 | C2C41339 | C2C41347 | C2C28533 | C2C28409 | C2C25696 | C2C24412 | C2C39763 | C2C31016 | |
| AS-2889 | C2C41341 | C2C41343 | C2C28531 | C2C28407 | C2C24410 | C2C25694 | C2C39765 | C2C31014 | C2C23698 | C2C28531 |
| AS-2890 | C2C28534 | C2C28410 | C2C20163 | C2C23700 | C2C2245 | C2C24413 | C2C25697 | C2C39764 | C2C31017 | C2C23699 |
| | C2C23699E | C2C20162 | C2C2244 | C2C41352 | C2C41354 | | | | | |
| AS-2891 | C2C41346 | C2C41344 | C2C39766 | C2C31015 | C2C28532 | C2C28408 | C2C20165 | C2C2261 | C2C25695 | C2C24411 |
| P-2291 | C2C27702 | C2C22825 | C2C27702 | C2C27702E | | | | | | |
| JEEP | | | | | | | | | | |
| A-3010 | 68258355AA | 68258355AB | 68029912AE | 68029912AC | 68029912AD | 68029911AB | | | | |
| AS-3021 | 68059904AE | 68059904AC | 68059904AD | 68059904AB | | | | | | |
| LAND ROVER | | | | | | | | | | |
| A-2202 | RKB101200 | | | | | | | | | |
| A-2611 | REB101740 | ANR4684 | | | | | | | | |
| A-2612 | RKB101460 | | | | | | | | | |
| A-2691 | REB101740 | ANR4684 | | | | | | | | |
| A-2692 | RKB101460 | | | | | | | | | |
| A-2831 | RKB500082 | RKB500080 | RKB000151 | RKB000150 | RKB500130 | RKB500240 | RKB500080K | | | |
| A-2933 | LR032563 | LR051700 | RNB000060 | RNB000740 | RNB500540 | RNB501340 | RNB501400 | RNB501520 | | |
| A-2934 | LR032570 | LR051702 | RNB000070 | RNB000750 | RNB500550 | RNB501350 | RNB501410 | RNB501530 | | |
| A-3025 | LR034262 | | | | | | | | | |
| A-3027 | R: LR044853 | | | | | | | | | |
| | L: LR052171 | | | | | | | | | |
| AS-2307 | RNB000740 | LR032563 | RNB000060 | RNB501520 | RNB501400 | RNB501340 | RNB500540 | | | |
| AS-2308 | RNB000750 | LR032570 | RNB000070 | RNB501530 | RNB501410 | RNB501350 | RNB500550 | | | |
| AS-2516 | LR032563 | RNB501520 | RNB501400 | RNB501340 | RNB500540 | | | | | |
| AS-2517 | LR032570 | RNB501530 | RNB501410 | RNB501350 | RNB500550 | | | | | |
| AS-2534 | LR041110 | LR038096 | LR016418 | RPD501100 | RPD501020 | LR032650 | | | | |
| AS-2757 | LR032560 | LR012859 | LR012860 | | | | | | | |
| AS-2758 | LR032567 | LR012885 | LR012886 | | | | | | | |
| AS-2761 | LR032648 | LR052867 | LR018190 | LR018191 | LR019993 | LR019994 | LR032647 | LR052866 | | |
| AS-2762 | R: LR032652 | LR020001 | LR023235 | | | | | | | |
| | L: LR032651 | LR020000 | LR023234 | | | | | | | |
| AS-2795 | LR032563 | RNB501520 | RNB501400 | RNB501340 | RNB500540 | | | | | |
| AS-2796 | LR032570 | RNB501530 | RNB501410 | RNB501350 | RNB500550 | | | | | |
| AS-2797 | LR012859 | LR012860 | LR032560 | | | | | | | |
| AS-2798 | LR012885 | LR012886 | LR032567 | | | | | | | |
| AS-2809 | RNB501580 | RNB501250 | RNB501620 | RNB501460 | RNB501600 | RNB501470 | RNB000857 | RNB000856 | RNB000858 | RNB501480 |
| | RNB501610 | LR016416 | | | | | | | | |
| AS-2961 | RNB000740 | LR032563 | LR051700 | RNB501520 | RNB000060 | RNB501400 | RNB501340 | RNB500540 | | |
| AS-2962 | RNB000750 | LR032570 | LR051702 | RNB501530 | RNB000070 | RNB501410 | RNB501350 | RNB500550 | | |
| AS-3067 | LR079515 | LR038800 | LR038802 | LR052773 | LR057250 | LR060132 | LR072445 | | | |
| AS-3068 | LR087091 | LR038804 | LR038806 | LR052775 | LR057256 | LR060133 | LR072458 | | | |
| AS-3069 | LR087083 | LR045100 | LR052784 | LR057253 | LR060399 | LR072450 | | | | |
| AS-3070 | LR087094 | LR044852 | LR052787 | LR057259 | LR060401 | LR072440 | | | | |
| P-2462 | RQL000014 | LR006201 | RQG000020 | RQL000011 | RQB000190 | RQL000010 | RQC000020 | | | |

| Arnott Item # | OEM # | | | | | | | | | |
|----------------------|---------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|
| LAND ROVER | | | | | | | | | | |
| AS-3204 | LR087083 | LR045100 | LR052784 | LR057253 | LR060399 | LR072450 | | | | |
| AS-3205 | LR087094 | LR044852 | LR052787 | LR057259 | LR060401 | LR072440 | | | | |
| P-2495 | RQG100041 | ANR4868 | | | | | | | | |
| P-2514 | ANR3731 | | | | | | | | | |
| P-2815 | LR061663 | LR045251 | LR044360 | LR041776 | LR032902 | LR023964 | LR038118 | LR038117 | LR038115 | LR038114 |
| | LR038148 | LR038116 | LR037065 | LR015303 | LR012705 | LR010376 | LR011837 | RQG500160 | LR010414 | RQG500150 |
| | RQG500130 | LR006200 | RQG500090 | RQG500080 | RQG500072 | RQG500071 | RQG500070 | RQG500019 | RQG500015 | RQG500018 |
| | RQG500016 | | | | | | | | | |
| P-3232 | LR041777 | LR010375 | LR015089 | LR010375 | LR025111 | RQG500040 | RQG500041 | RQG500140 | RQG500100 | |
| LEXUS | | | | | | | | | | |
| A-2949 | 4808035011 | 4809035011 | 4808035020 | 4808035010 | 4809035020 | 4809035010 | | | | |
| AS-2855 | 4801050153 | 4801050150 | 4801050152 | 4801050254 | 4801050253 | 4801050270 | 4801050291 | 4802050153 | 4802050150 | 4802050152 |
| | 4802050251 | 4802050253 | 4802050270 | 4802050290 | 4802050271 | 4802050291 | | | | |
| AS-2856 | R: 4808050153 | 4808050150 | 4808050152 | 4808050311 | 4808050310 | 4808050241 | 4808050240 | 4808050271 | 4808050270 | |
| | R (Sport): | 4808050261 | 4808050260 | 4808050164 | 4808050160 | 4808050161 | 4808050163 | | | |
| | L: 4809050153 | 4809050150 | 4809050152 | 4809050311 | 4809050310 | 4809050241 | 4809050240 | 4809050271 | 4809050270 | |
| | L (Sport): | 4809050261 | 4809050260 | 4809050164 | 4809050161 | 4809050163 | 4809050160 | | | |
| AS-2894 | 4801050110 | 4801050120 | 4801050130 | | | | | | | |
| AS-2895 | 4808050130 | 4808050120 | 4808050110 | | | | | | | |
| P-3186 | 48910-60021 | | | | | | | | | |
| P-3187 | 48910-50050 | | | | | | | | | |
| P-3188 | 48914-50031 | | | | | | | | | |
| SK-2812 | 4851060121 | 4851069415 | 4851069195 | | | | | | | |
| SK-2813 | 4853069485 | 4853069185 | 4853069205 | 4853069205 | 4853069205 | 4853069205 | | | | |
| LINCOLN | | | | | | | | | | |
| A-2105 | 3U2Z5580PA | 3U2Z5580BA | 6W1Z5560AA | 3U2Z5580AA | FOVY5560A | | | | | |
| A-2106 | E9AZ5310R | F1LY5310B | F1LY5310A | | | | | | | |
| A-2107 | F1LY5560B | F1LY5560A | | | | | | | | |
| A-2108 | 3U2Z5580FA | | | | | | | | | |
| A-2143 | 6L1Z3C199AA | | | | | | | | | |
| A-2148 | 3U2Z5580KA | | | | | | | | | |
| A-2153 | 3U2Z5580LA | | | | | | | | | |
| A-2173 | 3U2Z5580MA | 3U2Z5580HA | | | | | | | | |
| A-2174 | 3U2Z5310CA | 3U2Z5310DA | | | | | | | | |
| A-2212 | 3U2Z5580NA | 3U2Z5580JA | | | | | | | | |
| A-2220 | 3U2Z5580PA | 3U2Z5580BA | 6W1Z5560AA | 3U2Z5580AA | FOVY5560A | | | | | |
| A-2647 | 8L1Z5A891B | 7L1Z5A891B | | | | | | | | |
| A-2735 | 4L1Z5A891AA | | | | | | | | | |
| P-2210 | F7LZ5319AA | | | | | | | | | |
| P-2211 | F5OY5319A | F7OY5319B | | | | | | | | |
| P-2231 | FOLY5319-A | | | | | | | | | |
| P-2932 | 1L1Z5319AA | 1L1Z5319BA | 6L1Z5319AA | | | | | | | |
| P-2935 | F8VZ5319AA | | | | | | | | | |
| P-2936 | F6AZ5319AA | 8W1Z5319A | F1VY5319A | | | | | | | |
| P-2937 | 7L1Z5319AE | | | | | | | | | |
| SK-2225 | 3U2Z18125JA | F3LY18125A | F5LY19E616A | | | | | | | |
| MAYBACH | | | | | | | | | | |
| AS-2746 | 2403202013 | 2403201013 | | | | | | | | |
| AS-2747 | 2403201913 | 2403200913 | | | | | | | | |
| P-2192 | 2113200304 | 2203200104 | 2193200004 | 2113200104 | 211320030480 | | | | | |
| MERCEDES-BENZ | | | | | | | | | | |
| A-2575 | 1643204313 | 1643205813 | 1643204613 | 1643206013 | 1643205913 | 1643204413 | 1643204513 | 1643206113 | 164320581339 | 164320601339 |
| | 164320591339 | 164320581380 | 164320601380 | 164320591380 | 164320611380 | | | | | |
| A-2587 | 2513203113 | 2513203013 | 251320301380 | 251320311380 | | | | | | |
| A-2597 | 2513200425 | 2513200325 | 2513200025 | | | | | | | |
| A-2724 | 2113201625 | 2113200725 | 2113200825 | 2113201525 | 211320072580 | 211320082580 | 211320152580 | 211320162580 | 211320092580 | |
| A-2725 | 2113201325 | 2113201225 | 211320132580 | 211320122580 | | | | | | |
| A-2726 | 2113200925 | 211320092505 | 211320092580 | | | | | | | |
| A-2790 | 2123204425 | 2123200825 | 21232038 | | | | | | | |

ORDERING IS FAST & EASY!

CONTACT ARNOTT

| Arnott Item # | OEM # | | | | | | | | | | |
|-------------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|--|
| PORSCHE | | | | | | | | | | | |
| AS-3037 | 97034305215 | 97034305219 | | | | | | | | | |
| AS-3038 | 97034305108 | 97034305109 | 97034305110 | 97034305111 | 97034305112 | 97034305114 | 97034305115 | 97034305116 | 97034305117 | 97034305119 | |
| | 97034305122 | 97034305134 | 97034305135 | | | | | | | | |
| P-2496 | 4L0698007C | 7L0698853C | 95535890105 | 95535890104 | 4L0698007B | 4L0698007A | 4L0698007 | 7L0698853A | 7L0698853B | 7L8616006A | |
| | 7L0698853 | 7L8616006C | 7L8616007A | 7L8616007C | 7L8616007E | 7L8616007F | 95535890103 | 95535890102 | | | |
| SAAB | | | | | | | | | | | |
| A-2610 | 25815604 | 15125532 | 15276029 | 15183661 | 15183657 | 15159630 | 15090620 | 15089028 | | | |
| P-2857 | 25978169 | 25878674 | 25789710 | 15006679 | 15145230 | 15187099 | 15094346 | | | | |
| TOYOTA | | | | | | | | | | | |
| A-2949 | 4808035011 | 4809035011 | 4808035020 | 4808035010 | 4809035020 | 4809035010 | | | | | |
| AS-2855 | 4801050153 | 4801050150 | 4801050152 | 4801050254 | 4801050253 | 4801050270 | 4801050291 | 4802050153 | 4802050150 | 4802050152 | |
| | 4802050251 | 4802050253 | 4802050270 | 4802050290 | 4802050271 | 4802050291 | | | | | |
| P-3189 | 4891434021 | 4891434020 | | | | | | | | | |
| P-3190 | 4891434011 | 4891434010 | | | | | | | | | |
| P-3192 | 4891060021 | 4891060020 | | | | | | | | | |
| SK-2812 | 4851060121 | 4851069415 | 4851069195 | | | | | | | | |
| SK-2813 | 4853069485 | 4853069185 | 4853069205 | 4853069205 | 4853060071 | | | | | | |
| VOLKSWAGEN | | | | | | | | | | | |
| A-2523 | 95535850332 | 7L6616503B | 7L8616503B | 95535850331 | 95535850330 | 95535850321 | 95535850300 | 7L6616503A | 7L6616503 | | |
| A-2571 | 95535840431 | 95535840421 | 7L6616404B | 7L8616404B | 7L5616404E | 95535840410 | 95535840400 | 7L6616404A | 7L8616404A | 95535840430 | |
| | 95535840420 | 7L8616404 | 7L6616405 | | | | | | | | |
| A-2572 | 95535840331 | 95535840321 | 7L6616403B | 7L8616403B | 7L5616403E | 95535840310 | 95535840300 | 7L6616403A | 7L8616403A | 95535840330 | |
| | 95535840320 | 7L8616403 | 7L6616403 | | | | | | | | |
| AS-2580 | 3D0616040AC | 3D0616040AD | 3D0616040N | 3W0616040 | 3W5616040 | 3W7616040 | 3D0616040 | 3D5616040 | 3D7616040 | 3D0616040AA | |
| | 3D0616040AB | 3D0616040S | 3D0616040L | 3D0616040T | 3D0616040M | 3D0616040Q | 3D0616001H | 3D0616002J | 3D0616039Q | 3D0616039P | |
| | 3D0616040P | 3D0616040G | | | | | | | | | |
| AS-2581 | 3D0616039AD | 3D0616039N | 3D0616039AC | 3W0616039 | 3W5616039 | 3W7616039 | 3D0616039 | 3D5616039 | 3D7616039 | 3D0616039AA | |
| | 3D0616039AB | 3D0616039S | 3D0616039L | 3D0616039T | 3D0616039M | 3D0616039Q | 3D0616039P | 3D0616040Q | 3D0616040P | 3D0616001H | |
| | 3D0616002J | 3D0616039G | | | | | | | | | |
| AS-2892 | 3D0616040AC | 3D0616040AD | 3D0616040N | 30616040 | 35616040 | 37616040 | 3D0616040 | 3D5616040 | 3D7616040 | 3D0616040AA | |
| | 3D0616040AB | 3D0616040S | 3D0616040 | 3D0616040T | 3D0616040M | 3D0616040Q | 3D0616001 | 3D0616002J | 3D0616039Q | 3D0616039P | |
| | 3D0616040P | 3D0616040G | | | | | | | | | |
| AS-2893 | 3D0616039AD | 3D0616039N | 3D0616039AC | 30616039 | 35616039 | 37616039 | 3D0616039 | 3D5616039 | 3D7616039 | 3D0616039AA | |
| | 3D0616039AB | 3D0616039S | 3D0616039 | 3D0616039T | 3D0616039M | 3D0616039Q | 3D0616039P | 3D0616040Q | 3D0616040P | 3D0616001 | |
| | 3D0616002J | 3D0616039G | | | | | | | | | |
| P-2496 | 4L0698007C | 7L0698853C | 95535890105 | 95535890104 | 4L0698007B | 4L0698007A | 4L0698007 | 7L0698853A | 7L0698853B | 7L8616006A | |
| | 7L0698853 | 7L8616006C | 7L8616007A | 7L8616007C | 7L8616007E | 7L8616007F | 95535890103 | 95535890102 | | | |
| P-2740 | 3D0616005P | 3D0616005L | 3D0616005M | 3D0616007C | 3D0616007D | 3D0616007E | 3D0616005H | 3D0616005K | | | |



Products available at Arnott Authorised Distributors throughout the EU. Ask your local dealer or log onto our website and use the "Dealer Locator" at the top of the page - www.ArnottEurope.com.



Contact Arnott Europe Business Office:

Docterskampstraat 1E/1F
5222 AM 's-Hertogenbosche (NL)

Call: +31 (0)73 7850 580
 NL Phone: +31 (0)73 7850 580
 DE Phone: +49 (0)699 6759106
 UK Phone: +44 (0)203 3186124
 BE Phone: +32 (0)258 846 90
 ES Phone: +34 91 901 10 56
 Email: info@arnotteurope.com

Contact Arnott Inc. Business Office:

100 Sea Ray Drive
Merritt Island, FL 32953

Call: 321.868.3016
 Fax: 321.868.3703
 Email: info@arnottinc.com

Follow Us On:

Go to Arnott's dealer locator to find the Arnott Authorised Distributor nearest you. Contact the Arnott air suspension experts if you need assistance in finding a local authorised distributor or to answer product questions. Arnott's Customer Service team is available to assist you with what to order, product availability and any other questions you might have regarding Arnott's air suspension.

- ORDER WITH CONFIDENCE:**
- TÜV Rheinland Product Safety & Quality Certification
 - Satisfaction Guaranteed
 - Extensive Network of Authorised Distributors
 - Over 25 Years of Customer Satisfaction



ARNOTT TRANSFORMS GOOD RIDES INTO GREAT RIDES

ELEVATE YOUR RIDE.™

Motorcycle air suspension isn't just for ride height adjustability. Arnott's air suspension kits provide superior ride comfort, safety and luxury. Nothing will smooth out a chattering road, help eliminate painful bottoming or keep your rear tire firmly on the road like an Arnott Adjustable Air Suspension System. Arnott kits, with TruAIR™ Technology, will help turn a good ride into a GREAT ride.

To find out more about TruAIR Suspension visit arnottcycles.com

ARNOTT CYCLES.COM
+44 (0)203 3186124

LIFETIME WARRANTY

2017 Arnott Industries. All rights reserved. Make sure you follow all instructions and safety tips. All other trademarks are those of their respective owners.



Air Suspension Products

DOCTERSKAMPSTRAAT 1E / 1F
5222 AM 'S-HERTOGENBOSCH
THE NETHERLANDS

PH:+31 (0)73 7850 580 • UK:+44 (0)203 3186124 • ARNOTTEUROPE.COM